

Corrosion Inspection Report

Image: img138_jpg.rf.7e7c41ed1affe91d34993ac1bc57ba51.jpg

Generated on: report_26.pdf

Results

Corrosion Detected: PASS (4 spot(s))

Severity: High=1, Medium=0, Low=3

Original Image



Detected Corrosion

