

Corrosion Inspection Report

Image: img11_jpg.rf.5b3bee1524021488f28e3325da7c6bfd.jpg

Generated on: report_86.pdf

Detection Result:

(8 spot(s))

High=3, Medium=0, Low=5

Comments & Observations:

severely



Original Image



Detected + Markup