

Corrosion Inspection Report

Image: img61_jpg.rf.4e88909ec64ec528fc831dbcfb8e9481.jpg

Generated on: report_112.pdf

Detection Result:

(1 spot(s))

High=1, Medium=0, Low=0

