



Job Site

CRAWLEY RTW,
PRIESTLEY WAY,
CRAWLEY,
RH10 9NT

Job Information

Job Number	16944	Reference	475.100.
Logged	25/09/2024	Job Type	Contract - PUWER
Contact	Michael William	Tel.	01293 721800

Description

PUWER Inspections

Job Equipment

Equipment	Cust Equip	Visit	Status
0000152216 / Door / Powered Vertical	0000152216	1	Done
0000152236 / Door / Powered Vertical	0000152236	1	Done
0000152256 / Door / Powered Vertical	0000152256	1	Done
0000152276 / Door / Powered Vertical	0000152276	1	Done
0000152296 / Door / Powered Vertical	0000152296	1	Done
0000152316 / Door / Powered Vertical	0000152316	1	Done
0000152318 / Door / Powered Horizontal	0000152318	1	Done
0000152333 / Door / Shutter Electric	0000152333	1	Done
0000152373 / Door / Powered Horizontal	0000152373	1	Done

Labour Visits

Visit	Engineer	Date
1	Carmelo Belfiore	03/10/2024

Engineer Report

Engineer

Carmelo Belfiore





Overview				Site
Inspect N	88969	Page:	1/1	<div>CRAWLEY RTW</div> <div>PRIESTLEY WAY</div> <div>CRAWLEY</div> <div>RH10 9NT</div>
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152256	Door Powered Vertical		0000152256

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	The travel of the leading edge of the door within floor guide is compromised causing operation to stop when opening.
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore



Overview				Site
Inspect N	88950	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152333	Door Shutter Electric		0000152333

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore



Overview				Site
Inspect N	88954	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152316	Door Powered Vertical		0000152316

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore



Overview				Site	
Inspect N	88961	Page:	1/1		
Job No	16944				
Customer	AECOM				
Contact	Michael William	Date	03/10/2024		
Tel	01293 721800				
				CRAWLEY RTW	
				PRIESTLEY WAY	
				CRAWLEY	
				RH10 9NT	

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152296	Door Powered Vertical		0000152296

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore



Overview				Site
Inspect N	88966	Page:	1/1	<div>CRAWLEY RTW</div> <div>PRIESTLEY WAY</div> <div>CRAWLEY</div> <div>RH10 9NT</div>
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152276	Door Powered Vertical		0000152276

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore

Notice of Non-Examination

Overview				Site
Inspect N	88991	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			
Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000152236	Door Powered Vertical		0000152236	
Skipped Inspection				
Reason equipment was not inspected		Inoperative		

Engineer

Carmelo Belfiore



Notice of Non-Examination

Overview				Site
Inspect N	88993	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			
Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000152216	Door Powered Vertical		0000152216	
Skipped Inspection				
Reason equipment was not inspected		Inoperative		

Engineer

Carmelo Belfiore



Notice of Non-Examination

Overview				Site
Inspect N	88994	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

Asset Not Inspected

ISI Equipment No	Make / Model	Serial No	Client ID
0000152373	Door Powered Horizontal		0000152373

Skipped Inspection

Reason equipment was not inspected	Inoperative
------------------------------------	-------------

Engineer

Carmelo Belfiore



Notice of Non-Examination

Overview				Site
Inspect N	88995	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			
Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000152318	Door Powered Horizontal		0000152318	
Skipped Inspection				
Reason equipment was not inspected		Inoperative		

Engineer

Carmelo Belfiore

