



Overview				Site
Inspect N	63888	Page:	1/1	GREENFORD IND TETRIS A40 ROCKWARE AVENUE GREENFORD UB6 0AA
Job No	14875			
Customer	AECOM			
Contact	Muhammed Basathia	Date	22/05/2024	
Tel				

Fail

ISI Equipment No	Make / Model	Serial No	Client ID
20052024034	Dock System Leveller	609305	0000609305

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	The bottom hoist ram anchorage pin has become detached from its housing and should be suitably relocated and secured immediately and before further use.
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	The rated capacity should be clearly marked.
Tolerable - Observations	None



General Comments

N

Engineer

John Harding

Notice of Non-Examination

Overview				Site	
Inspect N	84292	Page:	1/1	OXFORD DO/OFF ROYAL MAIL HOUSE OXFORD OX1 1XX	
Job No	16334				
Customer	AECOM				
Contact	David Lyon	Date	12/09/2024		
Tel	01865 440815				
Asset Not Inspected					
ISI Equipment No		Make / Model		Serial No	Client ID
0000051267		Air Handling Unit (All)			0000051267
Skipped Inspection					
Reason equipment was not inspected			asset not found as confirmed by site manager Shahzad Ansar		

Engineer

John Harding

