



**Job Site**

CRAWLEY DO/RET,  
7 THE BOULEVARD,  
CRAWLEY,  
RH10 1AA

**Job Information**

<b>Job Number</b>	16946	<b>Reference</b>	1480.100.
<b>Logged</b>	25/09/2024	<b>Job Type</b>	Contract - PUWER
<b>Contact</b>	Nuno Dias	<b>Tel.</b>	01293 574001

**Description**

PUWER Inspections

**Job Equipment**

Equipment	Cust Equip	Visit	Status
000000000000150 / Door / Automatic Pedestrian	000000000000150	1	Done
000000000000151 / Door / Automatic Pedestrian	000000000000151	1	Done
0000160269 / Barrier / Traffic	0000160269	1	Done
0000160342 / Barrier / Traffic	0000160342	1	Done
0000680645 / Barrier / Traffic	0000680645	1	Done

**Labour Visits**

Visit	Engineer	Date
1	Carmelo Belfiore	03/10/2024

**Engineer Report**

**Engineer**

Carmelo Belfiore





Overview				Site	
Inspect N	89046	Page:	1/1		
Job No	16946				
Customer	AECOM				
Contact	Nuno Dias	Date	03/10/2024		
Tel	01293 574001				
				CRAWLEY DO/RET	
				7 THE BOULEVARD	
				CRAWLEY	
				RH10 1AA	

## Pass

ISI Equipment No	Make / Model	Serial No	Client ID
000000000000150	Door Automatic Pedestrian		000000000000150

### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



### General Comments

None

### Engineer

Carmelo Belfiore



Overview				Site
Inspect N	89047	Page:	1/1	<b>CRAWLEY DO/RET</b>  7 THE BOULEVARD  CRAWLEY  RH10 1AA
Job No	16946			
Customer	AECOM			
Contact	Nuno Dias	Date	03/10/2024	
Tel	01293 574001			

### Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000680645	Barrier Traffic		0000680645

### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



### General Comments

None

### Engineer

Carmelo Belfiore



Overview				Site	
Inspect N	89048	Page:	1/1		
Job No	16946				
Customer	AECOM				
Contact	Nuno Dias	Date	03/10/2024		
Tel	01293 574001				
				CRAWLEY DO/RET	
				7 THE BOULEVARD	
				CRAWLEY	
				RH10 1AA	

## Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000000000000151	Door Automatic Pedestrian		0000000000000151

### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



### General Comments

None

### Engineer

Carmelo Belfiore

## Notice of Non-Examination

Overview				Site
Inspect N	89049	Page:	1/1	<b>CRAWLEY DO/RET</b>  7 THE BOULEVARD  CRAWLEY  RH10 1AA
Job No	16946			
Customer	AECOM			
Contact	Nuno Dias	Date	03/10/2024	
Tel	01293 574001			
Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000160269	Barrier Traffic		0000160269	
Skipped Inspection				
Reason equipment was not inspected		Not located		

**Engineer**

Carmelo Belfiore



## Notice of Non-Examination

Overview				Site
Inspect N	89050	Page:	1/1	<b>CRAWLEY DO/RET</b>  7 THE BOULEVARD  CRAWLEY  RH10 1AA
Job No	16946			
Customer	AECOM			
Contact	Nuno Dias	Date	03/10/2024	
Tel	01293 574001			
Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000160342	Barrier Traffic		0000160342	
Skipped Inspection				
Reason equipment was not inspected		Not located		

**Engineer**

Carmelo Belfiore

