




Roof

REPORT ID
44995433

August 20, 2025

PROPERTY
3364 Vasquez Pl
Round Rock, TX 78665



© 2025 Eagle View Technologies, Inc. All Rights Reserved

Property Address

3364 Vasquez Pl
Round Rock, TX 78665

Measurements

Area:	42.9 SQ
Roof Facets:	20
Predominant Pitch:	8/12
Number of Stories:	>1
Ridges/Hips:	255'
Valleys:	117' 4"
Rakes:	128' 7"
Eaves:	230' 5"
Estimated Attic:	0 SQ
Roof Penetrations:	15
Roof Penetrations Perimeter:	44'
Roof Penetrations Area:	0.1 SQ

Contents

Lengths	1
Pitch (Degrees).....	2
Pitch (on 12)	3
Rafters	4
Azimuth	5
Area	6
Roof Penetrations	7
Imagery	8
Roofing Report Summary	11

Report Details

Report ID: 44995433

Prepared For

Divya Devadas
10900 NE 4th St Suite 80123
Bellevue, WA 98004
(855) 984-6590



Open in EagleView One™



Satisfaction Guaranteed
www.eagleview.com/Guarantee.aspx




Lengths


Ridges = 44' 2"
Hips = 210' 10"
Valleys = 117' 4"

Rakes = 128' 7"
Eaves = 230' 5"
Flashing = 40' 3"

Step flashing = 60' 3"
Parapets = 0'
Other = 0'



© 2025 Eagle View Technologies, Inc. All Rights Reserved




August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433




Pitch (Degrees)

In some cases, pitch labels have been removed for readability. Flat facets are labels 'F'.




© 2025 Eagle View Technologies, Inc. All Rights Reserved




Pitch (on 12)

In some cases, pitch labels have been removed for readability. Flat facets are labels 'F'.




© 2025 Eagle View Technologies, Inc. All Rights Reserved



Rafters


Rafter lengths (rounded to the nearest whole number) over 5 feet. In some cases, segment labels have been removed for readability. Some numbers are prefaced by “+” signs to avoid confusion when rotated (e.g. +6 and +9).




© 2024 Eagle View Technologies, Inc., All Rights Reserved.

Azimuth

The azimuth is the orientation of the structure to true north. In this diagram roof facet directions are labeled in degrees, with 0° (360°) as true north. Flat facets are labeled as 'F'.





© 2025 Eagle View Technologies, Inc. All Rights Reserved



Area


The area is measured in squares per roof facet. The values have been rounded to the nearest square.




August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433



Roof Penetrations



© 2025 Eagle View Technologies, Inc. All Rights Reserved



August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433



Imagery

These are images of the property taken from multiple angles.

TOP VIEW




NORTH SIDE



August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433



SOUTH SIDE



EAST SIDE



August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433



WEST SIDE



August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433



ROOFING REPORT SUMMARY

All Structures

Areas per Pitch

Roof Pitches	4/12	8/12
Area (SQ)	2.3	40.6
% of Roof	5.3%	94.7%

The table above lists each pitch on this roof and the total area and percent of the roof with that pitch.

Structure Complexity

Simple

Normal

Complex


Waste Calculation

NOTE: This waste calculation table is for asphalt shingle roofing applications. All values in the table below only include roof areas of 3/12 pitch or greater. For total measurements of all pitches, please refer to Lengths, Areas, and Pitches section below.

Waste %	0%	2%	7%	12%	15%	17%	19%	22%	27%
Area (m ²)	398	406	426	446	457	465	473	485	505
Squares *	43.00	44.00	46.00	48.33	49.33	50.33	51.33	52.33	54.66
Measured						Suggested			

*Squares are rounded up to the 1/3 of a square

Additional materials needed for ridge, hip, and starter lengths are not included in the above table. The provided suggested waste factor is intended to serve as a guide—actual waste percentages may differ based upon several variables that EagleView does not control. These waste factor variables include, but are not limited to, individual installation techniques, crew experiences, asphalt shingle material subtleties, and potential salvage from the site. Individual results may vary from suggested waste factor that EagleView has provided. The suggested waste is not to replace or substitute for experience or judgement as to any given replacement or repair work.



© 2025 EagleView Technologies, Inc. All Rights Reserved

Lengths, Areas and Pitches

Ridges = 44' 2" (6 Ridges)
Hips = 210' 10" (17 Hips)
Valleys = 117' 4" (8 Valleys)
Rakes† = 128' 7" (12 Rakes)
Eaves/Starkers‡ = 230' 5" (20 Eaves)
Drip Edge (Eaves + Rakes) = 359' (32 Lengths)
Parapet Walls = 0' (0 Lengths)
Flashing = 40' 3" (6 Lengths)
Step Flashing = 60' 3" (6 Lengths)
Total Roof Penetrations Area = 0.1 SQ
Total Roof Area Less Roof Penetrations = 42.8 SQ
Total Roof Penetrations Perimeter = 44'
Predominant Pitch = 8/12
Total Area (All Pitches) = 42.9 SQ

Total Roof Facets = 20

Total Roof Penetrations = 15

† Rakes are defined as roof edges that are sloped (not level).

‡ Eaves are defined as edges that are not sloped and level

Property Location

Longitude = -97.6134890
Latitude = 30.5677430

Notes

This was ordered as a residential property. There were no changes to the structure in past four years.

August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433



3364 Vasquez Pl, Round Rock, TX 78665

Report: 44995433

IMPORTANT LEGAL NOTICE AND DISCLAIMER**Notice and Disclaimer**

No Warranty: The Copyrighted Materials are provided to you "as is," and you agree to use it at your own risk.

EagleView Technologies makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise, including but not limited to, content, quality, accuracy, completeness, effectiveness, reliability, fitness for a particular purpose, usefulness, use or results to be obtained from the Copyrighted Materials.

Contractors agree to always conduct a preliminary site survey to verify Roof Report ordered. In the event of an error in a Report, your sole remedy will be a refund of the fees paid by you to obtain this Report.

August 20, 2025
Property Address:
3364 Vasquez Pl, Round Rock, TX 78665
Report: 44995433