



Invoice

Customer	Invoice No.	Case No.
HarperTroy	SO03256798	CAS-8588621-T9N7P2
Invoice Date	Sales Tax Included?	
2022-Mar-30	Yes	

Ship to
2955 Interstate 10 East, Beaumont, TX, 77702, UNITED STATES

Invoice to
2955 Interstate 10 East, Beaumont, TX, 77702, UNITED STATES

Remark
Dear Customer, After carrying out the damage assessment, we found that your product was malfunctioned. As your product is out of warranty, we will provide a paid repair service to you. We will either repair it or replace it with a product that's new or equivalent to new in both performance and reliability after payment has been received. For more information, please visit (<http://www.dji.com/service/policy>). If you have any questions or concerns regarding this quotation, or if you need any assistance regarding this case, such as changing your shipping address, feel free to reach out to us via repairfeedback.na@dji.com, thanks.

ITEM	QTY	UNIT PRICE	AMOUNT
Roll Axis Arm Module	1	25.00	25.00
Repair Service Fee	1	65.00	65.00
Shipping Cost			0.00
Discount			0.00
Sub Total Payment			90.00
Sales Tax (if applicable)			7.43
Grand Total Payment (USD)			97.43

DJI Service LLC
17301 Edwards Rd
Cerritos, CA 90703
United States

Customer Support Number: (818) 235-0789
Official Website: www.dji.com
Technical Support Email: support.us@dji.com