

26) Creep is noticed only at temp above  $0.4 T_m$  where recrystallisation occurs readily, therefore cold working has no significant effect and cannot be used for creep resistance.

Cold work can reduce the creep rate at the lower end of temperatures of interest while at higher temperatures creep rate is accelerated.