



Figures 146, 147

Post top lanterns which are damaged by wind may cause danger for nearby pedestrians, loose elements could fall down.



Figures 148, 149, 150

Figure 148: The in-ground light is not performing as it was designed, replacement would be required.

Figure 149: The electrical circuit looks like still in use and may cause fatalities in case someone may touch it.

Figure 150: In fact of poor quality or maintenance humidity is shown inside this path luminaire.