



Notes: Miner Slough at HWY 84 Bridge (cms)



*Prospect Island Restoration Project*

**Tidally averaged flow rate (GODIN filter)**

Project No. 11-1031

Created By: sjb

**Figure A-23**