



Notes: Miner Slough at HWY 84 Bridge (cms)



Prospect Island Restoration Project

# Tidally averaged flow rate (GODIN filter)

Project No. 11-1031

Created By: sjb

Figure A-23