

Does not punch software problem Ex: 24257698

TVS

problem solve
PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD

Head Office

DMS No. 3320

89, Bir Uttam C.R Datta road, Nasir Trade center Level-12, Banglamotor, Dhaka.

Ref.No: Ra F.R SI NO# 01 Date: 15.06.2021

Zone Name: Rangpur Engineer Name: Md: Hosan Ali

Approved by: Prabir Biswas (Head of Service & S/Parts)

Customer Name: Aminul islam ✓ Mobile No: 01918-077688

Address: Banglaheli, hakimpur, dingpur *Rangpur* Dealer Name: Milon bazar Rangpur ✓

Customer Complain:- CH NO Full # MD6M14LL2L4N00016 ✓

1. Rear Shockabsorber oil EN NO Full # OL4NL4800045 ✓

leakage Sale Date # 09.06.21 Present Kms # 1042

Date of Comp# 15.06.21

Date of Repair # 15.06.21 ✓

Model # TVS KING Duramax

Free Cupon service information

1st Free Service

2nd Free Service

3rd Free Service

Date

KMs

Date

KMs

Date

KMs

15.06.21

1042


Obserbation:- Rear lesft side Shockabsorber oil Leakage

Action Taken:- We did the tast left side rear shockabsorber oil leakage and has been canged from milon bazar dealer.

Failure Particular

SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G2090100	Rear Skockabsorber	01 pc	Gabrial		
2						
3						
4						
5						
6						

Failure Parts Photo



For Head Office Use

For
28/06/2021
Bill
24/6/21

Mitushar
24/06/2021

DMS complete