


<b>TVS</b>	<b>PRODUCT PERFORMANCE FEEDBACK REPORT</b>		
<b>IFAD</b> MOTORS LIMITED	<b>IFAD MOTORS LTD</b>		DMS NO:
	<b>Head Office</b>		<b>3148</b>

**IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208**





Ref.No:	Mar-261	F.R SI NO#	261	Date:	07.03.2021
Zone Name:	Cumilla	Engineer Name:	Md.Pabel Sarker	Mchanic Name:	Sumon Dali
Approved by:	Prabir Biswas (Head of Service,Spare Parts & Production)				

Customer Name:	Dulal	Mobile No:	01814302295
Address:	Sadar South, Cumilla	Dealer Name:	Adunik Motors
Customer Complain:-	CH NO Full #	MD6M14CL9K4P00051	Present Km
Vehicle is not started .	EN NO Full #	0L4PK4200358	Model #
	Sale Date #	25/01/2021	TVS King Duramex
	Date of Comp#	03.03.2021	1st PS Date
	Date of Repair#	03.03.2021	1st PS Kms
Free service information			
1st Free Service		2nd Free Service	
Date	KMs	Date	KMs
25.02.2021	1200		

**Observation:-** we checked & found that ignition coil assy shorts. *Reading 1?? primary resistance - 3.00 ohm coil cold*

**Action Taken:-** Require to replace this parts under warranty for approval. *hot condition 3.9 ohm out of 4 ohm*

Failure Particular						
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G4060370	IGNITION COIL ASSY	01			
2						
3						
4						

<b>Failure Parts Photo</b> 	<b>For Head Office Use</b>		
	Head of Service	Engineer	DMS
	 18/3/2021	 7.3.21	 07.03/2021 DMS complete