

Customer Code: 23806061

IFAD MOTORS LTD

DMS NO:

Head Office

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No: March-267

F.R SI NO#

267

Date: 18.03.2021

Zone Name: Cumilla

Engineer Name: Md.Pabel Sarker

Mchanic Name: Sumon Dali

Approved by: Prabir Biswas (Head of Service, Spare Parts &amp; Production)

Customer Name: Md. Vashani

Mobile No:

01302959386

Address: Kosba, B. baria

Dealer Name:

Modina Motors ✓

Customer Complain:-

CH NO Full #

MD6M14CL4L4N00003

Present Km

420 ✓

Rear Shock absorber Oil leakage.

EN NO Full #

0L4NL4X00034 ✓

Model #

TVS King Duramex Plus

Sale Date #

03.03.2021 ✓

Date of Comp#

18.03.2021

1St PS Date

1st PS Kms

Date of Repair#

Free service information

1St Free Service

2nd Free Service

3rd Free Service

Date

KMs

Date

KMs

Date

KMs

Observation:-


we checked &amp; found that Rear Shock absorber oil leakage.

Action Taken:- Require to replace this parts under warranty for approval.

Failure Particular

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G2090100	Rear Shock Absorber	01			
2						
3						
4						

Failure Parts Photo



For Head Office Use

Head of Service

Engineer

DMS

For  
02/05/2021  
DMS Not Punched

*[Signature]*

Mittra Datta  
02/05/2021