

IFAD MOTORS LTD

DMS NO:

Head Office

3252

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No:	Jan-252	F.R SI NO#	252	Date:	30.01.2021
Zone Name:	Cumilla	Engineer Name:	Md.Pabel Sarker	Mchanic Name:	Sumon Dali
Approved by:	Prabir Biswas (Head of Service, Spare Parts & Production)				
Customer Name:	S.Alam	Mobile No:	01783388969		
Address:	Akhaora, B.Baria	Dealer Name:	Modina Motors		
Customer Complain:-	CH NO Full #	MD6M14LA3K4K00580	Present Km	4321	
Front shock absorber oil leakage.	EN NO Full #	AK4KK4713745	Model #	TVS King Duramax	
	Sale Date #	06.09.2020			
	Date of Comp#	25.01.2021	1st PS Date	1st PS Kms	
	Date of Repair#				
Free service information					
1st Free Service		2nd Free Service		3rd Free Service	
Date	KMs	Date	KMs	Date	KMs
07.10.2020	1021	07.01.2021	3,899		

Observation:-

we checked & found that front shock absorber oil leakage.


Action Taken: Require to replace this parts under warranty for approval.

Failure Particular

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G4100180	Front Shock Absorber	01			
2						
3						
4						

Failure Parts Photo

For Head Office Use



Head of Service

Engineer

DMS

For
02/05/2021
DMS Punched

[Signature]

Mitru Saha
02/05/2021

DMS Complete

[Signature]
01/01/20