

Vehicle Labor and Part History

G P Automotive, Inc.

TDB 7/25/2022

Customer: Lisa Deriau

Vehicle: 1987 MERCEDES BENZ 560SL 5.6

VIN: WDBBA48DXHA061297

Unit/Fleet Num:

Phone:

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
48686	6/27/2022	154,018	RP	7/18/2022			
						Total:	405.76
Diagnose vehicle problem. Cranks but does not attempt to start. Checked fuel pressure should be enough to try to start. No spark. Checked							
LABOR: Diagnose engine cranks but will not start					2.00	2.00	340.00
40866	2/16/2016	146,339	KR	2/26/2016			
						Total:	1,714.03
There is a leak in the cooling system.							
LABOR: Inspect cooling system for leak.					10.50	10.50	1,039.50
107 501 22 82	Radiator Hose-Upper					1.00	14.83
116 200 03 15	Thermostat Kit - Behr					1.00	47.70
13 X 960	Drive Belt-Air Conditioni					1.00	17.35
10 X 750	Drive Belt-Air Pump					1.00	13.47
10 X 1005	Drive Belt-Alternator					1.00	14.84
10 X 1110	Drive Belt-Power Steering					2.00	26.90
107 501 24 82	Radiator Hose-Lower					1.00	155.74
116 200 17 01	Water pump					1.00	157.81
Q 103 0004	Coolant/Antifreeze - 1 Ga					1.00	42.30
33354	10/20/2011	120,425	MG	11/02/2011			
						CONVERTED INVOICE Total:	664.17
LABOR							
Replace front shocks per mike's recommendation last week.						1.00	97.00
The wiper motor is not working, please check and report. Wiper motor and linkage i s						2.30	223.10
Parts Sold							0.00
PARTS							
24-005241	Shock absorber					2.00	254.44
3391014207	Wiper insert,ea,123,late					2.00	16.00
31371	9/03/2010	114,095	20	9/03/2010			
						CONVERTED INVOICE Total:	407.28
LABOR							
Lube chassis as needed--c hange oil and filter (x) check brakes (x) check belts (x) check						0.30	16.50
Performed courtesy inspec tion - n/c.						0.01	0.00
Coolant and brake fluid l ast replaced nov 2007, both are due. All other maintenance up to							0.00
Flush brake fluid with ne w dot 4 fluid.						0.80	74.40
Cooling system flush proc edure. Includes using special cleaning agent in cooling system,						1.20	116.40
Parts Sold							0.00
PARTS							
15-40	Kendall motor oil 15w40					9.00	37.35
000 180 06 09	Oil filter kit					1.00	20.75
BRAKE FLUID	Dot 4 brake fluid, qt.					1.00	13.18
VP005	Cooling system cleaner					1.00	25.44
Q 1 03 0002	Antifreeze-mercedes-benz					2.00	48.00
30376	2/25/2010	109,792		2/25/2010			
						CONVERTED INVOICE Total:	5.48
LABOR							
Parts Sold							0.00
PARTS							

Vehicle history for the past 320 months.

Vehicle Labor and Part History

G P Automotive, Inc.

TDB 7/25/2022

Customer: Lisa Deriau

Vehicle: 1987 MERCEDES BENZ 560SL 5.6

VIN: WDBBA48DXHA061297

Unit/Fleet Num:

Phone:

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
126 827 14 98	Antenna seal					1.00	5.00
30338	2/18/2010	109,792		2/18/2010	CONVERTED INVOICE	Total:	98.55
LABOR							
	Parts Sold						0.00
PARTS							
Q 6 68 0249	Floor mat set					1.00	90.00
30262	2/04/2010	109,792	MG	2/05/2010	CONVERTED INVOICE	Total:	842.29
LABOR							
	Replace torn "a" pillar seal and hardtop seals passenger side. Check and adjust window					3.50	339.50
	Lube chassis as needed--change oil and filter (x) check brakes (x) check belts (x) check					0.30	16.50
	Customer says there is an oil burning smell. Check out oil leaks and report. Engine is					0.50	48.50
	Give customer estimate for new floor mats. New mats from mercedes \$90.						0.00
	Performed courtesy inspection - n/c.					0.01	0.00
	Parts Sold						0.00
PARTS							
15-40	Kendall motor oil					9.00	37.35
000 180 06 09	Oil filter kit					1.00	13.33
107 690 08 97	Pillar post seal r					1.00	185.51
107 720 06 78	Weatherstrip					1.00	101.00
26646	11/14/2007	107,844	CT	11/20/2007	CONVERTED INVOICE	Total:	1,007.10
LABOR							
	Perform 30,000 mile maintenance service as per mercedes benz factory checklist. In					5.00	440.00
	Check and give estimate for replacement of a pillar seal. Would need new a pillar seal						0.00
	Parts Sold						0.00
PARTS							
15-40	Kendall motor oil					9.00	31.41
ATF	Dexron automatic trans fl					8.00	22.08
90W	90w gear oil					3.00	12.00
000 989 88 03	Power steering fluid/mb					1.00	14.50
001 094 78 04	Air filter, v8					1.00	46.00
002 094 46 04	Air pump filter m/b					1.00	14.50
W9DC	Spark plug					8.00	20.00
BRAKE FLUID	Dot 4 brake fluid, qt.					1.00	11.94
Q 1 03 0002	Antifreeze-mercedes-benz					1.50	44.46
000 466 16 04	Power steering filter					1.00	15.00
126 271 10 80	Trans pan gasket, 722.3					1.00	17.50
126 277 02 95	Transmission filter, mb					1.00	49.50
002 477 44 01	Fuel filter mb, 81--					1.00	46.00
000 180 06 09	Oil filter kit					1.00	8.75
0 356 301 023	Plug connector					1.00	14.00
124 492 00 44	Exhaust hanger					2.00	17.00
116 492 00 82	Exhaust hanger, square					2.00	15.08
000 431 90 87	Brake reservoir cap					2.00	20.28
3 391 014 119	Wiper insert, ea					2.00	23.54
26416	10/01/2007	105,487	CT	10/01/2007	CONVERTED INVOICE	Total:	103.46

Vehicle history for the past 320 months.

Vehicle Labor and Part History

G P Automotive, Inc.

TDB 7/25/2022

Customer: Lisa Deriau

Vehicle: 1987 MERCEDES BENZ 560SL 5.6

VIN: WDBBA48DXHA061297

Unit/Fleet Num:

Phone:

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
LABOR							
						0.50	44.00
							0.00
PARTS							
107 750 00 42	Crankarm					1.00	27.11
107 750 00 66 9045	Crank arm pad					1.00	21.26
24403	9/06/2006	101,072	WH	9/07/2006	CONVERTED INVOICE Total:		330.23
LABOR							
						1.00	84.00
						1.50	138.00
						0.30	16.50
						1.00	0.00
							0.00
							0.00
							0.00
PARTS							
15-40	Kendall motor oil 15w40					8.00	23.68
104 180 01 09	Oil filter/ 104					1.00	9.75
INTERIORBULB	Bulb					4.00	14.00
23290	1/12/2006	99,301	CT	1/12/2006	CONVERTED INVOICE Total:		687.08
LABOR							
						0.40	33.60
						0.70	58.80
							0.00
						1.00	84.00
							0.00
							0.00
PARTS							
107 720 01 80	Moulding					1.00	120.00
009021 004207	Washer					2.00	6.00
304032 004002	Nut					1.00	3.00
001 988 76 81	Fastener,moulding					6.00	18.00
107 760 25 59	Coded door lock					1.00	278.00
EXTERIORBULB	Bulb					1.00	2.95
	Door panel clip					8.00	16.00
17403	12/09/2002	81,496	MG	12/13/2002	CONVERTED INVOICE Total:		683.92
LABOR							
						4.50	315.00
							0.00
PARTS							
107 720 07 46	Window regulator					1.00	270.00
107 725 01 25	Window rubber					1.00	30.75
16722	8/21/2002	81,496	MG	8/23/2002	CONVERTED INVOICE Total:		551.79
LABOR							
						2.00	150.00
						0.30	0.00

Vehicle history for the past 320 months.

Vehicle Labor and Part History

G P Automotive, Inc.

TDB 7/25/2022

Customer: Lisa Deriau

Vehicle: 1987 MERCEDES BENZ 560SL 5.6

VIN: WDBBA48DXHA061297

Unit/Fleet Num:

Phone:

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
Somewhere behind the dash board, most likely the center vent vacuum element or the							0.00
Parts Sold							0.00
PARTS							
107 830 27 85-88	Climate control module					1.00	342.00
107 830 27 85-88	Core received					1.00	
INTERIORBULB	Bulb					5.00	10.00
16500	7/16/2002	80,678	RH	7/16/2002	CONVERTED INVOICE Total:		170.38
LABOR							
Lube chassis as needed--c hange oil and filter (x) check brakes (x) check belts (x) check						0.30	16.50
Customer installed stereo . The memory function does not work and the ant enna doesn't							0.00
Air conditioner doesn't b low cold air. Do basic testing and report. Tested and found							0.00
A/c- preform air conditio ning check-up. Includes adding freon to system, a /c						1.50	105.00
Parts Sold							0.00
PARTS							
15-40	Kendall motor oil					9.00	18.00
000 180 06 09	Oil filter kit					1.00	8.50
15779	3/14/2002	74,398		3/14/2002	CONVERTED INVOICE Total:		27.02
LABOR							
Parts Sold							0.00
PARTS							
126 760 10 06	Key, master					1.00	24.95
14896	10/17/2001	74,398	MG	10/18/2001	CONVERTED INVOICE Total:		884.32
LABOR							
Replace broken radiator.						1.50	105.00
Sublet towing						1.00	48.00
Parts Sold							0.00
PARTS							
107 500 26 03	Radiator/oes					1.00	715.00
Q 1 03 0002	Antifreeze-mercedes-benz					1.00	14.50
14146	6/21/2001	72,791	MG	6/22/2001	CONVERTED INVOICE Total:		492.67
LABOR							
Lube chassis as needed--c hange oil and filter (x) check brakes (x) check belts (x) check						0.30	16.50
Brake pedal drifts to the floor. Car takes longer than normal distance to s top. Brake pads							0.00
Check brakes: road test vehicle and evaluate braking performance. Rem ove all wheels						0.50	35.00
Instrument cluster light is burned out. Also the tachometer does not work- needle does							0.00
Removed and replaced brak e master cylinder						1.40	98.00
Flush brake fluid with ne w dot 4 fluid.						0.60	42.00
Parts Sold							0.00
PARTS							
15-40	Kendall motor oil					9.00	18.00
000 180 06 09	Oil filter kit					1.00	8.50
004 430 75 01	Brake master cylinder					1.00	216.00
BRAKE FLUID	Dot 4 brake fluid, qt.					1.00	9.50
13801	4/25/2001	69,167		4/25/2001	CONVERTED INVOICE Total:		69.53

Vehicle history for the past 320 months.

Vehicle Labor and Part History

G P Automotive, Inc.

TDB 7/25/2022

Customer: Lisa Deriau

Vehicle: 1987 MERCEDES BENZ 560SL 5.6

VIN: WDBBA48DXHA061297

Unit/Fleet Num:

Phone:

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
LABOR							
							0.00
PARTS							
001 420 08 20	Front pads, 560sl					1.00	64.20
11958	7/11/2000	69,167	RH	7/12/2000	CONVERTED INVOICE Total:		614.12
LABOR							
	Car towed in. Engine runs poorly and idle speed varies high and low. Also hesitation on					3.00	195.00
	Sublet towing					1.00	42.50
	Customer requesting top c addy for the hard top. Part special ordered and in stock.						0.00
	Freight					1.00	20.00
	Vehicle battery was dead. On initial testing battery failed load test. Performed extended						0.00
	Basic electrical check-out t: includes load test battery, check out starter draw, and test					0.50	32.50
	Parts Sold						0.00
PARTS							
CART-ALL	Hd/top storage cart w/cvr					1.00	169.95
000 156 59 10	Plug wire resistor 1k					4.00	98.00
10139	9/22/1999	68,846	RH	9/22/1999	CONVERTED INVOICE Total:		389.67
LABOR							
	Lube chassis as needed--change oil and filter (x) check brakes (x) check belts (x) check					0.30	16.50
	Inspect timing chain and advise. Removed valve covers- found chain and gears					2.50	155.00
	Driver's window has wind noise and binds up against the hardtop. Inspect and advise						0.00
	During l of inspect found fuel leaking at the fuel pump fittings. Due to the inherent safety					0.50	31.00
	Roadtested and checked for wind noise- found noise present at left and right window to					0.60	37.20
	Parts Sold						0.00
PARTS							
15-40	Kendall motor oil					9.00	15.75
001 180 06 09	Oil filter, mb v8					1.00	8.50
116 050 18 11	Chain tensioner, v8, late					1.00	79.50
	009 545 40 28 plug hsg					1.00	1.86
	009 545 41 28 plug cover					1.00	1.65
10034	9/08/1999	68,341		9/08/1999	CONVERTED INVOICE Total:		101.79
LABOR							
	Right front window is down and won't go up. Inspect and advise. Initially found battery					1.00	62.00
	Parts Sold						0.00
PARTS							
000 820 83 10	Switch, window					1.00	29.50
7826	10/19/1998	0		10/19/1998	CONVERTED INVOICE Total:		107.16
LABOR							
	Parts Sold						0.00
PARTS							
MT-93	Battery					1.00	98.95
MT-93	Core received					1.00	