

Vehicle diagnostic report

Shop Name: Russell Emptage
Address: 92230
Telephone:
Email :
Fax:

License #: abc1
Make: DEMO
Model:
Year:
VIN: 1E4GEAK12FT00001X
Mileage: 35565 (km)
Vehicle Software Version: V14.80
Diagnostic Application Version: V3.07.010
Test Time: 2017-05-17 13:40:50
Diagnostic path: Health Report



Diagnostic Result

Fault		(8)
ECM(Engine Control Module)	(4)	Abnormal
P0303 Misfiring of Cylinder 3(P0303) P2097 Throttle Valve Block(Ice up) P0401 EGR Valve A Flow Insufficient Detected P0174 System A/F Ratio too Lean (Bank 2)		
TCM(Transmission Control Module)	(3)	Abnormal
P2500 The Transmission Has an Impermissible Transmission Ratio. P2502 The Gear is Implausible or the Transmission is Slipping. P2211 The Selector Lever is in an Intermediate Position.		
ABS(Anti-lock Braking System)	(2)	Abnormal
C1141 Brake Pressure Sensor B34 C1201 A7/7s1(BAS Release Switch) : Electrical Fault		
SRS(Supplemental Inflatable Restraint System)	(3)	Abnormal
B1878 Airbag-OFF-Lampe Fehlerart B1868 The Coding for the Ignition Circuit with Component R12/22(Left Rear Window Airbag Ignition Squib) is Faulty. B1019 The Ignition Circuit with Component R12/11(Left Rear Side Airbag Ignition Squib) Has Short Circuit to Positive.		
		Current
		Current
		Stored

BCM(Body Control Module)	(3)	Abnormal
	B2277 Detecting Vehicle Submersion B2282 Vehicle Speed Signal B2323 RR-Door Motor ECU Communication Stop	
IMM(Immobilizer)	(3)	Abnormal
	B2775 Interior Verification (to Theft Deterrent ECU / Smart Key ECU) B2776 Steering Lock Motor B2795 Unmatched Key Code	
TPMS(Tire Pressure Monitoring System)	(2)	Abnormal
	C1501 Tire Pressure Sensor 1 Internal C1502 Tire Pressure Sensor 2 Internal	
SAS(Steering Angle System)	(3)	Abnormal
	C1630 SAS Timeout C2205 SAS Internal Error C121A SAS Initialization	
Normal	(1)	
BMS(Battery Manager System)		Normal