


DISPOSAL

HINT:

- Use the same procedures for the RH side and LH side.
- The procedures listed below are for the LH side.
- A bolt without torque specification is a standard bolt (see page 03-2)



1. DISPOSE OF HOOD SUPPORT ASSY LH

- (a) Horizontally fix the stay in a vise with the piston-rod pulled out.
- (b) Wearing safety glasses, gradually cut a part between A and B as shown in the illustration using a metal saw to gradually release the gas.

Specification:

Area	Measurement
a	80 mm (3.15 in.)
b	20 mm (0.80 in.)

CAUTION:

Be careful to cover the area that is being cut as there is a possibility that metal debris could be blown out by the gas (the gas is colorless, odorless and harmless).