

## Location Summary Report

<b>Client Name:</b> Windsor -ESSEX Community Housing Corporation (CHC)							<b>Building Address:</b> 1323 Tilston Ave												
							<b>Building Name / Description:</b> Bridgeview I /												
<b>Location Name:</b> 1287 Askin Ave. - Attic							<b>Location Number:</b> 9128709				<b>Area of Location:</b> 700			<b>Floor:</b> 2					
<b>Consultant Name:</b> ECOH							<b>Last Survey Date:</b> 2016-04-04				<b>Last Re-assessment Date:</b>								

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER		RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS							
1.0	Walls	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
2.0	Floor	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
3.0	Ceiling	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
4.0	Structure	Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
5.0	Ducts	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
6.0	Mechanical	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
7.0	Other	Fiberglass	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
8.0	Piping	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		

**Comments :**