

## Location Summary Report

<b>Client Name:</b> Windsor -ESSEX Community Housing Corporation (CHC)							<b>Building Address:</b> 1323 Tilston Ave												
							<b>Building Name / Description:</b> Bridgeview I /												
<b>Location Name:</b> 1181 Askin Ave							<b>Location Number:</b> 27				<b>Area of Location:</b> 800			<b>Floor:</b> 1					
<b>Consultant Name:</b>							<b>Last Survey Date:</b> 2016-04-04				<b>Last Re-assessment Date:</b>								

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER		RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Floor Tiles	VFT6	12" X 12" Beige with Brown, Yellow and Blue Streak	N	A	200	0	0	200	SF			v	0000	None Detected	None Detected	Priority 3	
1.1	Floor	Vinyl Sheet Flooring	VSF2	Beige with stoney pattern	Y	A	50	0	0	50	SF			v	005-ASB	None Detected	None Detected	Priority 3	
1.2	Floor	Hard Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.0	Walls	Plaster	N/A	Plaster	N	A	100	0	0	100	SF			s	008-ASB	None Detected	None Detected	Priority 3	
3.0	Ceiling	Plaster	N/A	Plaster	N	C	800	0	0	800	SF			v	008-ASB	None Detected	None Detected	Priority 3	
4.0	Structure	Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Other	Heat Shield	N/A	Heat Shield	Y	D	2	0	0	2	SF			v	009-ASB	Chrysotile 40%	Confirmed Asbestos	Priority 2	

**Comments :** Detached - 2 Story with 3 Bedrooms

1.0 - Vinyl Floor Tiles (VFT6) are same as VFT2 in Bridgeview II sample # 002-ASB (none detected) in kitchen and Hallways

7.0 - Heat Shield leftover on vents