

Location Summary Report

Client Name: Windsor –ESSEX Community Housing Corporation (CHC)							Building Address: 4365 Wyandotte St. E.												
							Building Name / Description: Riggs Manor /												
Location Name: Garbage Room							Location Number: 44116				Area of Location: 150 SF			Floor: 1					
Consultant Name: ECOH							Last Survey Date: 2016-08-10				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER		RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Floor Tiles	VFT 1	12" x 12" Beige With Grey Streaks	N	A	150	0	0	150	SF			s	005-ASB	Chrysotile 2%	Confirmed Asbestos	Priority 3	
2.0	Ceiling	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
3.0	Structure	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
4.0	Piping	Fiberglass/Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Ducts	Fiberglass/Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Mechanical	Fiberglass/Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Walls	Concrete Block	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.1	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N	A	200	0	0	200	SF			s	002-ASB	Chrysotile 2%	Confirmed Asbestos	0	

Comments :