

Location Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: 255 Riverside Drive												
							Building Name / Description: Raymond Desmarais Bldg /												
Location Name: Basement Stairwell							Location Number: 1				Area of Location: 100 SF			Floor:					
Consultant Name: ECOH							Last Survey Date: 2016-02-18				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with Brown Streaks & Mastic	N	A	100	0	0	100	SF			v	009-ASB	Chrysotile 2%	Confirmed Asbestos	Priority 3	
2.0	Ceiling	Lay-in-Ceiling Tiles	CT4	2'x4' Faux 2'x2'	N	C	100	0	0	100	SF			v	017-ASB	None Detected	None Detected	Priority 3	
3.0	Walls	Plaster	N/A	Plaster	N	A	100	0	0	100	%			v	001-ASB	None Detected	None Detected	Priority 3	
4.0	Structure	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Piping	Fibreglass	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Ducts	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Mechanical	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
9.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	

Comments : 1- VFT None Detected, Mastic ACM (2%)