

Location Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: Various Addresses												
							Building Name / Description: Bridgeview I /												
Location Name: 1181 Askin Ave. - Basement							Location Number: 9118101				Area of Location: 600			Floor: 0					
Consultant Name:							Last Survey Date: 2016-04-04				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Concrete(Poured)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.1	Ducts	Heat Shield	N/A	Heat Shield	Y	C	0	0	1	1	SF			v	009-ASB	Chrysotile 60%	Confirmed Asbestos	Priority 1	
3.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
4.0	Structure	Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Ceiling	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Walls	Concrete Block	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.1	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N	A	200	0	0	200	SF		SF	v	006-ASB	None Detected	None Detected	Priority 4	
7.0	Mechanical	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	

Comments : Heat Shield - Leftover Residue on Duct