

Location Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: Various Addresses												
							Building Name / Description: Bridgeview I /												
Location Name: 1291 Rankin Ave. - Basement							Location Number: 9129101				Area of Location: 600			Floor: 0					
Consultant Name: ECOH							Last Survey Date: 2016-04-04				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST	
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N	A	100	0	0	100	%			s	006-ASB	None Detected	None Detected	Priority 3	
2.0	Structure	Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
3.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
4.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
5.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
6.0	Floor	Concrete(Poured)	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
7.0	Ceiling	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
8.0	Mechanical	Not Insulated	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		

Comments :