

Summary of Asbestos Bulk Samples

Client Name: Windsor –ESSEX Community Housing Corporation (CHC)							Building Address: 255 Riverside Drive					
							Building Name / Description: Raymond Desmarais Bldg /					
DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
001-ASB	16313-255RIV-ASB-01A	100	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected	None Detected	Layer 1 - Skim Coat Layer 2- Rough Coat
	16313-255RIV-ASB-01B	120	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		Layer 1 - Skim Coat Layer 2- Rough Coat
	16313-255RIV-ASB-01C	101	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-01D	1400	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-01E	1700	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-01F	1115	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	N/A		Layer 1 - Skim Coat Layer 2- Rough Coat
	16313-255RIV-ASB-01G	2108	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	N/A		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
002-ASB	16313-255RIV-ASB-02A	108	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A	None Detected	
	16313-255RIV-ASB-02B	108	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-02C	117	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-02D	120	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-02E	2111	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A		
003-ASB	16313-255RIV-ASB-03A	1700	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	Chrysotile	2	N/A	N/A	Confirmed Asbestos	
	16313-255RIV-ASB-03B	1500	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	N/A	Not Analyzed	N/A	N/A		Stopped Positive
	16313-255RIV-ASB-03C	1200	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	N/A	Not Analyzed	N/A	N/A		Stopped Positive
	16313-255RIV-ASB-03D	1100	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	N/A	Not Analyzed	N/A	N/A		Stopped Positive
	16313-255RIV-ASB-03E	1000	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	N/A	Not Analyzed	N/A	N/A		Stopped Positive

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
004-ASB	16313-255RIV-ASB-04A	2	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A	None Detected	
	16313-255RIV-ASB-04B	2	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-04C	2	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-04D	3	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-04E	3	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-04F	2201	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-04G	2201	Walls	Foundation Texture	N/A	Foundation Texture	N/A	None Detected	N/A	N/A		
005-ASB	16313-255RIV-ASB-05A	109	Piping	Parging Cement Insulation	N/A	Parging Cement Insulation	Chrysotile	40	N/A	N/A	Confirmed Asbestos	Parging Cement Fittings
	16313-255RIV-ASB-05B	109	Piping	Parging Cement Insulation	N/A	Parging Cement Insulation	N/A	Not Analyzed	N/A	N/A		Stop Positive
	16313-255RIV-ASB-05C	109	Piping	Parging Cement Insulation	N/A	Parging Cement Insulation	N/A	Not Analyzed	N/A	N/A		Stop Positive
006-ASB	16313-255RIV-ASB-06A	1505	Walls	Caulking	Caulking 1	Exterior Expansion caulking (Grey)	N/A	None Detected	N/A	N/A	None Detected	Exterior Expansion Caulking-Grey
	16313-255RIV-ASB-06B	1403	Walls	Caulking	Caulking 1	Exterior Expansion caulking (Grey)	N/A	None Detected	N/A	N/A		Exterior Expansion Caulking-Grey
	16313-255RIV-ASB-06C	203	Walls	Caulking	Caulking 1	Exterior Expansion caulking (Grey)	N/A	None Detected	N/A	N/A		Exterior Expansion Caulking-Grey

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
007-ASB	16313-255RIV-ASB-07A	1505	Walls	Caulking	Caulking 2	Exterior Balcony Door Caulking	N/A	None Detected	N/A	N/A	None Detected	Exterior Expansion Caulking-White
	16313-255RIV-ASB-07B	1403	Walls	Caulking	Caulking 2	Exterior Balcony Door Caulking	N/A	None Detected	N/A	N/A		Exterior Expansion Caulking-White
	16313-255RIV-ASB-07C	203	Walls	Caulking	Caulking 2	Exterior Balcony Door Caulking	N/A	None Detected	N/A	N/A		Exterior Expansion Caulking-White
008-ASB	16313-255RIV-ASB-08A	2111	Floor	Vinyl Floor Tiles	VFT1	12"x12" Grey with Dark Grey & White Streaks + Mastics	N/A	None Detected	N/A	None Detected	None Detected	Layer 1-VFT & Layer 2 - Mastic
	16313-255RIV-ASB-08B	2111	Floor	Vinyl Floor Tiles	VFT1	12"x12" Grey with Dark Grey & White Streaks + Mastics	N/A	None Detected	N/A	N/A		Layer 1-VFT & Layer 2 - Mastic
	16313-255RIV-ASB-08A	2111	Floor	Vinyl Floor Tiles	VFT1	12"x12" Grey with Dark Grey & White Streaks + Mastics	N/A	None Detected	N/A	N/A		Layer 1-VFT & Layer 2 - Mastic
009-ASB	16313-255RIV-ASB-09A	1604	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with Brown Streaks & Mastic	N/A	None Detected	Chrysotile	2	Confirmed Asbestos	Layer 1 VFT (None Detected) Layer 2 Mastic (ACM)
	16313-255RIV-ASB-09B	124	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with Brown Streaks & Mastic	N/A	None Detected	N/A	Not Analyzed		Layer 1 VFT (None Detected) Layer 2 Mastic (ACM)
	16313-255RIV-ASB-09C	121	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with Brown Streaks & Mastic	N/A	None Detected	N/A	Not Analyzed		Layer 1 VFT (None Detected) Layer 2 Mastic (ACM)

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
010-ASB	16313-255RIV-ASB-10A	303	Floor	Vinyl Floor Tiles	VFT3	12"x12" Beige with Brown Lines & Mastic	Chrysotile	2	Chrysotile	2	Confirmed Asbestos	Layer 1 VFT Layer 2 Mastic (Both 2% ACM)
	16313-255RIV-ASB-10B	2111	Floor	Vinyl Floor Tiles	VFT3	12"x12" Beige with Brown Lines & Mastic	N/A	Not Analyzed	N/A	Not Analyzed		Stop Positive
	16313-255RIV-ASB-10C	1806	Floor	Vinyl Floor Tiles	VFT3	12"x12" Beige with Brown Lines & Mastic	N/A	Not Analyzed	N/A	Not Analyzed		Stop Positive
011-ASB	16313-255RIV-ASB-11A	120	Floor	Vinyl Floor Tiles	VFT4	12"x12" Beige with Brown & Yellow Streaks & Mastic	Chrysotile	2	N/A	None Detected	Confirmed Asbestos	Layer-1 VFT (ACM) and Layer-2 is mastic
	16313-255RIV-ASB-11B	120	Floor	Vinyl Floor Tiles	VFT4	12"x12" Beige with Brown & Yellow Streaks & Mastic	N/A	Not Analyzed	N/A	None Detected		Stop Positive
	16313-255RIV-ASB-11C	120	Floor	Vinyl Floor Tiles	VFT4	12"x12" Beige with Brown & Yellow Streaks & Mastic	N/A	Not Analyzed	N/A	None Detected		Stop Positive
012-ASB	16313-255RIV-ASB-12A	1906	Floor	Vinyl Sheet Flooring	VSF1	Square Flower Pattern	N/A	None Detected	N/A	N/A	None Detected	
	16313-255RIV-ASB-12B	1906	Floor	Vinyl Sheet Flooring	VSF1	Square Flower Pattern	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-12A	1906	Floor	Vinyl Sheet Flooring	VSF1	Square Flower Pattern	N/A	None Detected	N/A	N/A		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
013-ASB	16313-255RIV-ASB-13A	124	Floor	Vinyl Sheet Flooring	VSF2	Small Grey/White Squares	N/A	None Detected	N/A	None Detected	None Detected	Layer 1 VSF and Layer 2 Mastic
	16313-255RIV-ASB-13B	124	Floor	Vinyl Sheet Flooring	VSF2	Small Grey/White Squares	N/A	None Detected	N/A	None Detected		Layer 1 VSF and Layer 2 Mastic
	16313-255RIV-ASB-13C	124	Floor	Vinyl Sheet Flooring	VSF2	Small Grey/White Squares	N/A	None Detected	N/A	None Detected		Layer 1 VSF and Layer 2 Mastic
014-ASB	16313-255RIV-ASB-14A	108	Ceiling	Lay-in-Ceiling Tiles	CT1	2'x4' Small Pinhole Small Fissure	N/A	None Detected	N/A	N/A	None Detected	
	16313-255RIV-ASB-14B	108	Ceiling	Lay-in-Ceiling Tiles	CT1	2'x4' Small Pinhole Small Fissure	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-14C	800	Ceiling	Lay-in-Ceiling Tiles	CT1	2'x4' Small Pinhole Small Fissure	N/A	None Detected	N/A	N/A		
015-ASB	16313-255RIV-ASB-15A	108	Ceiling	Lay-in-Ceiling Tiles	CT2	2'x4' Lengthwise Fissure	Amosite	2	N/A	N/A	Confirmed Asbestos	
	16313-255RIV-ASB-15B	800	Ceiling	Lay-in-Ceiling Tiles	CT2	2'x4' Lengthwise Fissure	N/A	Not Analyzed	N/A	N/A		Stop Positive
	16313-255RIV-ASB-15C	800	Ceiling	Lay-in-Ceiling Tiles	CT2	2'x4' Lengthwise Fissure	N/A	Not Analyzed	N/A	N/A		Stop Positive
016-ASB	16313-255RIV-ASB-16A	108	Ceiling	Lay-in-Ceiling Tiles	CT3	2'x4' Widthwise Fissure	N/A	None Detected	N/A	N/A	None Detected	
	16313-255RIV-ASB-16B	800	Ceiling	Lay-in-Ceiling Tiles	CT3	2'x4' Widthwise Fissure	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-16C	800	Ceiling	Lay-in-Ceiling Tiles	CT3	2'x4' Widthwise Fissure	N/A	None Detected	N/A	N/A		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
017-ASB	16313-255RIV-ASB-17A	100	Ceiling	Lay-in-Ceiling Tiles	CT4	2'x4' Faux 2'x2'	N/A	None Detected	N/A	N/A	None Detected	
	16313-255RIV-ASB-17B	100	Ceiling	Lay-in-Ceiling Tiles	CT4	2'x4' Faux 2'x2'	N/A	None Detected	N/A	N/A		
	16313-255RIV-ASB-17B	100	Ceiling	Lay-in-Ceiling Tiles	CT4	2'x4' Faux 2'x2'	N/A	None Detected	N/A	N/A		