

## Location Summary Report

<b>Client Name:</b> Client2		<b>Building Address:</b> 255 Riverside Drive																	
		<b>Building Name / Description:</b> Raymond Desmarais Bldg /																	
<b>Location Name:</b> Location1		<b>Location Number:</b> 0						<b>Area of Location:</b> 123						<b>Floor:</b> 2					
<b>Consultant Name:</b>		<b>Last Survey Date:</b> 2016-02-24						<b>Last Re-assessment Date:</b>											

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Floor Tiles	VFT6	9x9 blue	Y	B	300	200	50	550	SF	testsss		s001	Confirmed Asbestos	Confirmed Asbestos	Priority 1		
1.1	Structure	Steel	N/A	Steel	N	C	233	50	44	327	SF	testing sub		s001	Confirmed Asbestos	Confirmed Asbestos	Priority 1		
2.0	Ceiling	Lay-in-Ceiling Tiles	CT1	2x4 white with pink backing textured finish	Y	B	500	100	10	610		test		s1001	<L.O.D ( Chrysotile 0.4% )	<L.O.D	Priority 2		
2.1	Walls	Wall Covering	N/A	Wall Covering	Y	A	200	150	150	500	SF	hj		s00f23	Confirmed Asbestos ( Amosite 0.6 )	Confirmed Asbestos	Priority 2		
3.0	Walls	Wall Covering	N/A	Wall Covering	N	E	100	100	100	300	SF	ee	v	s001	Non Detected ( Chrysotile 0.4 )		Priority 2		
3.1	Ceiling	Painted	N/A		Y	C	100	0	0	100	SF		v	s001	Confirmed Asbestos ( Chrysotile 0.5% )	Confirmed Asbestos	Priority 1		
4.0	Piping	Painted	N/A		Y	D	300	150	100	550	SF	test	v	9500	Presumed Asbestos	Presumed Asbestos	Priority 2		

**Comments :** 1- VFT is ACM (2%) and Mastic None detected.  
 2-Limited access above plaster ceiling