

Client Name: Windsor Essex Community Housing Corporation (CHC)	Site Location: Various Addresses , Windsor, Ontario Bridgeview I (Various Addresses) – District #2	Project No. 16313-09
--	---	--------------------------------




Photo No. 1.	
Date: April 11, 2016	
Location: 1275 Rankin Attic (Loc. 09-1275-10)	
Description: Non-asbestos attic insulation	

Photo No. 2.	
Date: April 11, 2016	
Location: 1275 Rankin Kitchen (Loc. 09-1275-02)	
Description: Asbestos-containing Vinyl Floor Tile 1 (VFT1) – 12”x12” Beige with Black Veins.	


Client Name: Windsor Essex Community Housing Corporation (CHC)	Site Location: Various Addresses , Windsor, Ontario Bridgeview I (Various Addresses) – District #2	Project No. 16313-09
--	---	--------------------------------

Photo No. 3.	
Date: April 11, 2016	
Location: 1306 Rankin Kitchen (Loc. 09-1306-02)	
Description: Non-asbestos Vinyl Floor Tile 2 (VFT2) – 12”x12” Beige with Dark Streaks	

Photo No. 4.	
Date: April 11, 2016	
Location: 1306 Rankin Basement (Loc. 09-1306-01)	
Description: Asbestos-containing Vinyl Floor Tile 3 (VFT3) – 9”x9” Black with Light Brown Streaks	

Client Name: Windsor Essex Community Housing Corporation (CHC)	Site Location: Various Addresses , Windsor, Ontario Bridgeview I (Various Addresses) – District #2	Project No. 16313-09
--	---	--------------------------------

Photo No. 5.	
Date: April 11, 2016	
Location: 1306 Rankin Washroom (Loc. 09-1306-03)	
Description: Non-asbestos Vinyl Sheet Floor 1 (VSF1) – Square Pattern	

Photo No. 6.	
Date: April 11, 2016	
Location: 1339 Rankin Washroom (Loc. 09-1339-03)	
Description: Non-asbestos Vinyl Sheet Floor 2 (VSF2) – Beige with Stoney Pattern	



Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 7.

Date:
April 11, 2016

Location:
1291 Rankin Hallway
(Loc. 09-1291-04)

Description:
Non-asbestos Vinyl Floor
Tile 4 (VFT4) – 12”x12”
Beige with Brown Marks



Photo No. 8.

Date:
April 11, 2016

Location:
1014 Rankin
(Loc. 09-1014-03)

Description:
Non-asbestos Vinyl
Sheet Floor 3 (VSF3) –
Grey





Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 9.

Date:
April 11, 2016

Location:
1291 Rankin Living
Room
(Loc. 09-1291-05)

Description:
Non-asbestos texture
finish on plaster



Photo No. 10.

Date:
April 11, 2016

Location:
1339 Rankin
Basement
(Loc. 09-1339-01)

Description:
Asbestos-containing
Heat Shield residue
observed in POOR
condition





Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 11.

Date:
April 11, 2016

Location:
1181 Askin Basement
(Loc. 09-1181-01)

Description:
Asbestos-containing
Heat Shield residue
observed in POOR
condition



Photo No. 12.

Date:
April 11, 2016

Location:
2300 Girardot
Basement
(Loc. 09-2300-01)

Description:
Asbestos-containing
Heat Shield around
vents observed in
POOR condition

