

Development Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: 255 Riverside Drive					
Development: Raymond Desmarais Bldg							District: 1					
SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		
Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with Brown Streaks & Mastic	111,115,117,121,124,123,1,410,415,814,905,1011,1115,1403,1604,1712,1801,2010	N	a	15480		Chrysotile 2%	Confirmed Asbestos	Priority 3	
Floor	Vinyl Floor Tiles	VFT3	12"x12" Beige with Brown Lines & Mastic	113,203,214,215,303,307,308,601,705,814,917,1005,1207,1505,2102,1806	N	b	14000		Chrysotile 2%	Confirmed Asbestos	Priority 3	
Floor	Vinyl Floor Tiles	VFT4	12"x12" Beige with Brown & Yellow Streaks & Mastic	114,120,121,2102	N	b	1200		Chrysotile 2%	Confirmed Asbestos	Priority 3	
Ceiling	Lay-in-Ceiling Tiles	CT2	2'x4' Lengthwise Fissure	108,112,120,121,800,2100	N	c	4520		Amosite 2%	Confirmed Asbestos	Priority 3	

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)								Building Address: 1323 Tilston Ave				
Development: Bridgeview I								District: 2				
SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		
Floor	Vinyl Floor Tiles	VFT1	12"x12" Beige with black veins	53	N	a	400		Chrysotile 2%	Confirmed Asbestos	Priority 3	
Floor	Vinyl Floor Tiles	VFT3	9"x 9" Black with light brown streak	19	N	a	80	0	Chrysotile 2%	Confirmed Asbestos	Priority 3	

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	HAZAROUS CONTENT		PRIORITY	ESTIMATED COST
									RESULTS	HAZARD		

