

Location Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: 255 Riverside Drive												
							Building Name / Description: Raymond Desmarais Bldg /												
Location Name: Unit 1906 (1 Bedroom)							Location Number: 1906				Area of Location: 500 SF			Floor: 19					
Consultant Name: ECOH							Last Survey Date: 2016-02-18				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Sheet Flooring	VSF1	Square Flower Pattern	Y	A	50	0	0	50	SF			s	012-ASB	No Asbestos	No Asbestos	Priority 3	
2.0	Floor	Carpet	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
3.0	Floor	Vinyl Floor Tiles	VFT5	Unknown Vinyl Floor Tiles	Y	E	250	0	0	250	SF			v	9500	Presumed Asbestos	Presumed Asbestos	Priority 3	
4.0	Ceiling	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N	C	250	0	0	250	SF			v	002-ASB	None Detected	None Detected	Priority 3	
5.0	Ceiling	Plaster	N/A	Plaster	N	C	250	0	0	250	SF			v	001-ASB	None Detected	None Detected	Priority 3	
6.0	Walls	Plaster	N/A	Plaster	N	A	100	0	0	100	%			v	001-ASB	None Detected	None Detected	Priority 3	
7.0	Structure	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
9.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
10.0	Mechanical	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
11.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	

Comments : 3.0 - VFT5 (unknown vinyl floor tiles) are present under the carpet.