

Summary of Asbestos Bulk Samples

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)								Building Address: 1323 Tilston Ave				
								Building Name / Description: Bridgeview I /				
DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
001-ASB	16313-09-ASB-01A	9127502	Floor	Vinyl Floor Tiles	VFT1	12"x12" Beige with black veins	Chrysotile	2	N/A	None Detected	Confirmed Asbestos	
	16313-09-ASB-01B	9127503	Floor	Vinyl Floor Tiles	VFT1	12"x12" Beige with black veins	N/A	Not Analyzed	N/A	None Detected		
	16313-09-ASB-01C	9127504	Floor	Vinyl Floor Tiles	VFT1	12"x12" Beige with black veins	N/A	Not Analyzed	N/A	None Detected		
002-ASB	16313-09-ASB-02A	9130602	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with dark streaks	N/A	None Detected	N/A	None Detected	None Detected	
	16313-09-ASB-02B	9130602	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with dark streaks	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-02C	9130602	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with dark streaks	N/A	None Detected	N/A	None Detected		Layer 1 VFT, Layer 2 is black mastic and Layer 3 is yellow mastic

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
003-ASB	16313-09-ASB-03A	9130601	Floor	Vinyl Floor Tiles	VFT3	9"x 9" Black with light brown streak	Chrysotile	2	N/A	N/A	Confirmed Asbestos	
	16313-09-ASB-03B	9130601	Floor	Vinyl Floor Tiles	VFT3	9"x 9" Black with light brown streak	N/A	Not Analyzed	N/A	N/A		
	16313-09-ASB-03C	9130601	Floor	Vinyl Floor Tiles	VFT3	9"x 9" Black with light brown streak	N/A	Not Analyzed	N/A	None Detected		
004-ASB	16313-09-ASB-04A	9130102	Floor	Vinyl Floor Tiles	VFT4	12"x 12" Beige with brown marks	N/A	None Detected	N/A	None Detected	None Detected	
	16313-09-ASB-04B	9129104	Floor	Vinyl Floor Tiles	VFT4	12"x 12" Beige with brown marks	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-04C	9133902	Floor	Vinyl Floor Tiles	VFT4	12"x 12" Beige with brown marks	N/A	None Detected	N/A	None Detected		
005-ASB	16313-09-ASB-05A	9133903	Floor	Vinyl Sheet Flooring	VSF2	Beige with stoney pattern	N/A	None Detected	N/A	N/A	None Detected	
	16313-09-ASB-05B	9133903	Floor	Vinyl Sheet Flooring	VSF2	Beige with stoney pattern	N/A	None Detected	N/A	N/A		
	16313-09-ASB-05C	9133903	Floor	Vinyl Sheet Flooring	VSF2	Beige with stoney pattern	N/A	None Detected	N/A	N/A		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
006-ASB	16313-09-ASB-06A	9129101	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A	None Detected	
	16313-09-ASB-06B	9129101	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A		
	16313-09-ASB-06C	9127501	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	None Detected	N/A	N/A		
007-ASB	16313-09-ASB-07A	9129105	Ceiling	Texture Finish	N/A	Texture Finish	N/A	N/A	N/A	Not Analyzed	None Detected	
	16313-09-ASB-07B	9129105	Ceiling	Texture Finish	N/A	Texture Finish	N/A	None Detected	N/A	N/A		
	16313-09-ASB-07C	9129105	Ceiling	Texture Finish	N/A	Texture Finish	N/A	None Detected	N/A	N/A		
008-ASB	16313-09-ASB-08A	9218605	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected	None Detected	
	16313-09-ASB-08B	9127706	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-08C	997202	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-08D	9118103	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-08E	9130108	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-08F	9130602	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		
	16313-09-ASB-08G	9127507	Walls	Plaster	N/A	Plaster	N/A	None Detected	N/A	None Detected		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
009-ASB	16313-09-ASB-09A	9130601	Ducts	Heat Shield	N/A	Heat Shield	Chrysotile	60	N/A	N/A	Confirmed Asbestos	
	16313-09-ASB-09B	9130601	Ducts	Heat Shield	N/A	Heat Shield	N/A	Not Analyzed	N/A	N/A		
	16313-09-ASB-09C	9130601	Ducts	Heat Shield	N/A	Heat Shield	N/A	Not Analyzed	N/A	N/A		