

## Location Summary Report

<b>Client Name:</b> Windsor -ESSEX Community Housing Corporation (CHC)						<b>Building Address:</b> 255 Riverside Drive													
						<b>Building Name / Description:</b> Raymond Desmarais Bldg /													
<b>Location Name:</b> Basement Mechanical Room						<b>Location Number:</b> 10001				<b>Area of Location:</b> 4000 SF				<b>Floor:</b> Basement					
<b>Consultant Name:</b> ECOH						<b>Last Survey Date:</b> 2016-02-18				<b>Last Re-assessment Date:</b>									

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER		RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.0	Ceiling	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
3.0	Walls	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
4.0	Structure	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Piping	Fiberglass	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Piping	Polyvinyl Chloride(PVC)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
9.0	Mechanical	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
10.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	

**Comments :**