

Location Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: 255 Riverside Drive												
							Building Name / Description: Raymond Desmarais Bldg /												
Location Name: Janitor's Supply							Location Number: 111				Area of Location: 120 SF			Floor: 1					
Consultant Name: ECOH							Last Survey Date: 2016-02-18				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER		RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS							
1.0	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with Brown Streaks & Mastic	N	B	120	0	0	120	SF			v	010-ASB	Confirmed Asbestos	Confirmed Asbestos	Priority 3		
2.0	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	Y	C	120	0	0	120	SF			v	003-ASB	Chrysotile 2%	Confirmed Asbestos	Priority 3		
3.0	Walls	Plaster	N/A	Plaster	N	B	50	0	0	50	%			v	001-ASB	None Detected	None Detected	Priority 4		
4.0	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N	B	50	0	0	50	%			v	002-ASB	None Detected	None Detected	Priority 4		
5.0	Structure	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
6.0	Piping	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
7.0	Ducts	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
8.0	Mechanical	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		
9.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-		

Comments :