

## Location Summary Report

<b>Client Name:</b> Windsor –ESSEX Community Housing Corporation (CHC)							<b>Building Address:</b> 255 Riverside Drive												
							<b>Building Name / Description:</b> Raymond Desmarais Bldg /												
<b>Location Name:</b> Corridor							<b>Location Number:</b> 2000				<b>Area of Location:</b> 2000 SF			<b>Floor:</b> 20					
<b>Consultant Name:</b> ECOH							<b>Last Survey Date:</b> 2016-02-18				<b>Last Re-assessment Date:</b>								

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST	
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Ceramic Tiles	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.0	Floor	Carpet	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
3.0	Ceiling	Texture Finish(Texture Coat)	N/A	Texture Finish(Texture Coat)	Y	C	2000	0	0	2000	SF			v	003-ASB	Chrysotile 2%	Confirmed Asbestos	Priority 3	
4.0	Walls	Plaster	N/A	Plaster	N	A	100	0	0	100	%			v	001-ASB	None Detected	None Detected	Priority 3	
5.0	Structure	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Piping	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Ducts	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Mechanical	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
9.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	

**Comments :** No access above ceiling, ACM may be present above ceiling and concealed areas.