

Location Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)							Building Address: 255 Riverside Drive												
							Building Name / Description: Raymond Desmarais Bldg /												
Location Name: Recycling Storage							Location Number: 109				Area of Location: 200 SF			Floor: 1					
Consultant Name:							Last Survey Date: 2016-02-18				Last Re-assessment Date:								

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST	
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.0	Ceiling	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
3.0	Walls	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
4.0	Structure	Concrete	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Piping	Fibreglass	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Piping	Parging Cement on Fittings	N/A	Parging Cement on Fittings	Y	B	4	0	0	4	Each			s	005-ASB	Chrysotile 40%	Confirmed Asbestos	Priority 3	
8.0	Ducts	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
9.0	Mechanical	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
10.0	Other	Not Found	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	

Comments :