



**Client Name:**  
Windsor Essex Community Housing  
Corporation (CHC)

**Site Location:**  
140 Bridge Avenue, Windsor, Ontario  
Ashgrove Manor Apartment Building– District #5

**Project No.**  
16313-41

**Photo No. 1.**

**Date:**  
August 9, 2016

**Location:**  
Basement Corridor  
(Loc. 41-001)

**Description:**  
Non-asbestos Vinyl  
Floor Tile 1 (VFT1) –  
12”x12” Beige with  
Light and Dark Beige  
Flecks. **Asbestos-**  
**containing** mastic  
may be present.



**Photo No. 2.**

**Date:**  
August 9, 2016

**Location:**  
Unit 415  
(Loc. 41-415)

**Description:**  
**Asbestos-containing**  
Vinyl Floor Tile 2  
(VFT2) – 12”x12”  
Beige with Grey  
Indents (2%  
**Chrysotile**), with  
**asbestos-containing**  
mastic (2%  
**Chrysotile**)





**Client Name:**  
Windsor Essex Community Housing  
Corporation (CHC)

**Site Location:**  
140 Bridge Avenue, Windsor, Ontario  
Ashgrove Manor Apartment Building– District #5

**Project No.**  
16313-41

**Photo No. 3.**

**Date:**  
August 9, 2016

**Location:**  
Washroom  
(Loc. 41-118)

**Description:**  
Non-asbestos Vinyl  
Floor Tile 3 (VFT3) –  
12”x12” Beige with  
Brown and Grey  
Flecks. **Asbestos-**  
**containing** mastic  
may be present.



**Photo No. 4.**

**Date:**  
August 9, 2016

**Location:**  
5<sup>th</sup> Floor Laundry  
(Loc. 41-516)

**Description:**  
Non-asbestos Vinyl  
Floor Tile 4 (VFT4) –  
12”x12” Beige with  
Brown Flecks, with  
**asbestos-containing**  
mastic (1%  
**Chrysotile**)





**Client Name:**  
Windsor Essex Community Housing  
Corporation (CHC)

**Site Location:**  
140 Bridge Avenue, Windsor, Ontario  
Ashgrove Manor Apartment Building– District #5

**Project No.**  
16313-41

**Photo No. 5.**

**Date:**  
August 9, 2016

**Location:**  
Unit 1110  
(Loc. 41-1110)

**Description:**  
Non-asbestos Vinyl  
Floor Tile 6 (VFT6) –  
12”x12” Beige with  
Sparse Tan and White  
Flecks. **Asbestos-**  
**containing** mastic  
may be present.




**Photo No. 6.**

**Date:**  
August 9, 2016

**Location:**  
Craft Room  
(Loc. 41-115)

**Description:**  
**Asbestos-containing**  
Vinyl Floor Tile 7  
(VFT7) – 12”x12”  
Beige with Brown  
Streaks (**2%  
Chrysotile**).  
**Asbestos-containing**  
mastic may be  
present.







**Client Name:**  
Windsor Essex Community Housing  
Corporation (CHC)

**Site Location:**  
140 Bridge Avenue, Windsor, Ontario  
Ashgrove Manor Apartment Building– District #5

**Project No.**  
16313-41

**Photo No. 7.**

**Date:**  
August 9, 2016

**Location:**  
Office Area  
(Loc. 41-108)

**Description:**  
Non-asbestos Ceiling  
Tile 1 (CT1) – 2'x4'  
Small and Medium  
Random Pinholes



**Photo No. 8.**

**Date:**  
August 9, 2016

**Location:**  
15<sup>th</sup> Floor Corridor  
(Loc. 41-1500)

**Description:**  
Non-asbestos Ceiling  
Tile 2 (CT2) – 2'x4'  
Textured





**Client Name:**  
Windsor Essex Community Housing  
Corporation (CHC)

**Site Location:**  
140 Bridge Avenue, Windsor, Ontario  
Ashgrove Manor Apartment Building– District #5

**Project No.**  
16313-41

**Photo No. 9.**

**Date:**  
August 9, 2016

**Location:**  
First Floor Corridor  
(Loc. 41-100)

**Description:**  
Non-asbestos Ceiling  
Tile 3 (CT3) – 2'x4'  
Short Hooked  
Random Fleck and  
Pinhole



**Photo No. 10.**

**Date:**  
August 9, 2016

**Location:**  
Office Area  
(Loc. 41-108)

**Description:**  
Non-asbestos Ceiling  
Tile 4 (CT4) – 2'x4'  
Small and Medium  
Dimple







**Client Name:**  
Windsor Essex Community Housing  
Corporation (CHC)

**Site Location:**  
140 Bridge Avenue, Windsor, Ontario  
Ashgrove Manor Apartment Building– District #5

**Project No.**  
16313-41

**Photo No. 11.**

**Date:**  
August 9, 2016

**Location:**  
Parking Garage  
(Loc. 41-004)

**Description:**  
Non-asbestos sprayed  
fireproofing

