

Summary of Asbestos Bulk Samples

Client Name: Windsor –ESSEX Community Housing Corporation (CHC)								Building Address: 4365 Wyandotte St. E.				
								Building Name / Description: Riggs Manor /				
DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
001-ASB	16313-44-ASB-01A	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A	None Detected	Exterior Finish-317 BALCONY
	16313-44-ASB-01B	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A		Exterior Finish-310 BALCONY
	16313-44-ASB-01C	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A		Exterior Finish-207 BALCONY
	16313-44-ASB-01D	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A		Exterior Finish-201 BALCONY
	16313-44-ASB-01E	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A		Exterior Finish-St 2 EXTERIOR
	16313-44-ASB-01F	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A		Exterior Finish-St 2 EXTERIOR
	16313-44-ASB-01G	0	Walls	Exterior Finishes	N/A	Exterior Finishes	N/A	None Detected	N/A	N/A		Exterior Finish-St 2 EXTERIOR

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
002-ASB	16313-44-ASB-02A	104	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	Chrysotile	2	N/A	N/A	Confirmed Asbestos	
	16313-44-ASB-02B	201	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		Positive Stop (Not Analyzed)
	16313-44-ASB-02C	110	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		Positive Stop (Not Analyzed)
	16313-44-ASB-02D	120	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		Positive Stop (Not Analyzed)
	16313-44-ASB-02E	300	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		Positive Stop (Not Analyzed)
	16313-44-ASB-02F	100	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		Positive Stop (Not Analyzed)
	16313-44-ASB-02G	116	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		Positive Stop (Not Analyzed)
003-ASB	16313-44-ASB-03A	126	Ceiling	Lay-in-Ceiling Tiles	CT 1	2'x4' Lengthwise Fissures and Pinholes	N/A	None Detected	N/A	N/A	None Detected	<0.25% Chrysotile
	16313-44-ASB-03B	100	Ceiling	Lay-in-Ceiling Tiles	CT 1	2'x4' Lengthwise Fissures and Pinholes	N/A	None Detected	N/A	N/A		<0.25% Chrysotile
	16313-44-ASB-03C	300	Ceiling	Lay-in-Ceiling Tiles	CT 1	2'x4' Lengthwise Fissures and Pinholes	N/A	None Detected	N/A	N/A		<0.25% Chrysotile

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
004-ASB	16313-44-ASB-04A	100	Ceiling	Lay-in-Ceiling Tiles	CT 2	2'x4' Dimple and Pinhole	N/A	None Detected	N/A	N/A	None Detected	
	16313-44-ASB-04B	200	Ceiling	Lay-in-Ceiling Tiles	CT 2	2'x4' Dimple and Pinhole	N/A	None Detected	N/A	N/A		
	16313-44-ASB-04C	300	Ceiling	Lay-in-Ceiling Tiles	CT 2	2'x4' Dimple and Pinhole	N/A	None Detected	N/A	N/A		
005-ASB	16313-44-ASB-05A	116	Floor	Vinyl Floor Tiles	VFT 1	12" x 12" Beige With Grey Streaks	Chrysotile	2	N/A	None Detected	Confirmed Asbestos	
	16313-44-ASB-05C	116	Floor	Vinyl Floor Tiles	VFT 1	12" x 12" Beige With Grey Streaks	N/A	Not Analyzed	N/A	None Detected		
	16313-44-ASB-05C	119	Floor	Vinyl Floor Tiles	VFT 1	12" x 12" Beige With Grey Streaks	N/A	Not Analyzed	N/A	None Detected		
006-ASB	16313-44-ASB-06A	104	Floor	Vinyl Floor Tiles	VFT 2	12" x 12" Beige with Brown and White Flecks	N/A	None Detected	N/A	None Detected	None Detected	
	16313-44-ASB-06B	310	Floor	Vinyl Floor Tiles	VFT 2	12" x 12" Beige with Brown and White Flecks	N/A	N/A	N/A	N/A		
	16313-44-ASB-06C	121	Floor	Vinyl Floor Tiles	VFT 2	12" x 12" Beige with Brown and White Flecks	N/A	N/A	N/A	N/A		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
007-ASB	16313-44-ASB-07A	221	Floor	Vinyl Floor Tiles	VFT 3	12"x12" Beige with Brown Streaks	Chrysotile	2	N/A	None Detected	Confirmed Asbestos	
	16313-44-ASB-07B	321	Floor	Vinyl Floor Tiles	VFT 3	12"x12" Beige with Brown Streaks	N/A	Not Analyzed	N/A	N/A		
	16313-44-ASB-07C	321	Floor	Vinyl Floor Tiles	VFT 3	12"x12" Beige with Brown Streaks	N/A	Not Analyzed	N/A	None Detected		
008-ASB	16313-44-ASB-08A	317	Floor	Vinyl Floor Tiles	VFT 4	12"x12" Beige with Brown and White Streaks	Chrysotile	2	N/A	None Detected	Confirmed Asbestos	
	16313-44-ASB-08B	207	Floor	Vinyl Floor Tiles	VFT 4	12"x12" Beige with Brown and White Streaks	N/A	Not Analyzed	N/A	None Detected		
	16313-44-ASB-08C	201	Floor	Vinyl Floor Tiles	VFT 4	12"x12" Beige with Brown and White Streaks	N/A	Not Analyzed	N/A	None Detected		