



Legend

01


HMIS Location Number



Location of Asbestos-Containing Mechanical Insulation



Location of Asbestos-Containing Vermiculite



Location of Asbestos-Containing Ceiling Tiles

Please Note:
ASBESTOS CONTAINING Vermiculite is present within the exterior concrete block wall cavities throughout this facility.

Drywall Joint Compound (DJC) have been identified as ASBESTOS CONTAINING throughout the building.

All information relating to room size and location is approximate and for visual aid only. ECOH does not guarantee the drawing to be complete, absolute, accurate or current. The drawing should not be used by any party in lieu of obtaining architectural drawings.

Figure 1



Sutton District High School

20798 Dalton Road
Sutton West, Ontario

Ground Floor Plan

CLIENT: York Region District School Board

PROJECT NUMBER: 15785-35 DATE: September 2015 DRW BY: MM


CAD FILE: FIG1-6 P15785-35-Sutton District HS SCALE: Not to Scale CHK BY: ADP



ECOH
Environmental Consulting
Occupational Health


- Floor System: VFT (Vinyl Floor Tile): Non Friable
Asbestos Containing Material
Ceiling System: CT (Ceiling Tiles): Non Friable
Asbestos Containing Material
SEE PAGE 79 OF THE REPORT

- Floor System: VFT (Vinyl Floor Tile): Non Friable
Asbestos Containing Material
- Piping System: PCF (Parging Cement Fittings): Friable
Asbestos Containing Material
SEE PAGE 132 OF THE REPORT





- Other System: Chalkboard: Presumed Non Friable
Asbestos Containing Material
- Ceiling System: CT (Ceiling Tiles): Non Friable
Asbestos Containing Materials
- Structure System: DJC (Drywall Joint Compound):
Non-Friable Asbestos Containing Material
[SEE PAGE 42 OF THE REPORT](#)



- Legend
- 01

HMIS Location Number
- Location of Asbestos-Containing Mechanical Insulation
- Location of Asbestos-Containing Vermiculite
- Location of Asbestos-Containing Ceiling Tiles

Please Note:
ASBESTOS CONTAINING Vermiculite is present within the exterior concrete block wall cavities throughout this facility.

Drywall Joint Compound (DJC) have been identified as ASBESTOS CONTAINING throughout the building.

All information relating to room size and location is approximate and for visual aid only. ECOH does not guarantee the drawing to be complete, absolute, accurate or current. The drawing should not be used by any party in lieu of obtaining architectural drawings.

Figure 2



Sutton District High School

20798 Dalton Road
Sutton West, Ontario

Second Floor Plan

CLIENT: York Region District School Board		
PROJECT NUMBER: 15785-35	DATE: September 2015	DRW BY: MM
CAD FILE: FIG1-6 P15785-35-Sutton District HS	SCALE: Not to Scale	CHK BY: ADP

