

DESIGNATED SUBSTANCES ASSESSMENT

**Bridgeview I – District #2
Various Addresses
Windsor, Ontario**

Prepared For:

Windsor Essex Community Housing Corporation
945 McDougall Street, P.O. Box 1330
Windsor, Ontario
N9A 6R3

Presented by:

ECOH
75 Courtneypark Drive West, Unit 1
Mississauga, Ontario

**RFP No.: RFP 15-09
Building Code: 09
ECOH Project No.: 16313**

November 1, 2016

TABLE OF CONTENTS

1.0	INTRODUCTION AND OVERVIEW	1
2.0	METHODOLOGY AND SCOPE	1
3.0	SUMMARY OF FINDINGS	2
4.0	CONCLUSIONS AND RECOMMENDATIONS	4
5.0	LIMITATIONS OF ASSESSMENT	5
6.0	CLOSURE	6

APPENDICES

Appendix I	Survey Drawings
Appendix II	Inventory of Identified Designated Substances
Appendix III	Observation Report (Photographs)
Appendix IV	Results of Bulk Sample Analysis for Asbestos and Lead

1.0 INTRODUCTION AND OVERVIEW

ECOH Management Inc. (ECOH) was retained by the Windsor Essex Community Housing Corporation (CHC) to conduct a designated substances assessment of Bridgeview I development (single family homes/duplexes – various addresses) in Windsor, Ontario (hereby referred to as the “facility” or “development”). The assessment was performed to establish the location and type of designated substances incorporated in the facility’s structure(s) and its finishes, and to provide recommendations, as necessary, to fulfil requirements set forth under the Ontario Occupational Health and Safety Act and associated regulations.

This designated substance assessment (DSA) was performed for the purposes of long-term management of designated substances contained within building materials, and not necessarily for construction or renovation purposes depending on the nature of the work being performed. As this assessment was carried out under normal use of the facilities, a more detailed and intrusive assessment would be required if the exposure conditions change such as during construction, demolition and renovations as required by OHSA s30. Data (information) generated by this assessment can however, be used to determine if a more detailed assessment is or is not needed prior to construction, demolition and renovation, and identify the designated substance(s) of concern based on the type and location of the activity to be undertaken.

Mr. Mahir Bholat & Mr. Steven Gore of ECOH performed the fieldwork on April 11, 2016.

2.0 METHODOLOGY AND SCOPE

The methodology and scope of the Designated Substances Assessment (DSA) completed at the facility are detailed in the overview document titled “Designated Substances Assessment Scope of Work and Methodology Report”, dated July 2016, prepared by ECOH. A copy of this document is available from the CHC, and forms part of this report by reference. The overview document is to be read in conjunction with this report to form the complete report for the facility.

The subject development consists of single family homes with 72 tenant units measuring approximately 53,600 square feet (total buildings) and was reportedly originally constructed in 1952. ECOH completed a visual assessment of seventeen (17) randomly selected tenant units (approx. 20% of total units in this facility), for the presence of designated substances at the development. The following is a list of tenant units/homes specifically investigated as part of this assessment:

- 1014 Rankin (Loc. 09-1014)
- 1306 Rankin (Loc. 09-1306)

- 1339 Rankin (Loc. 09-1339)
- 1056 Askin (Loc. 09-1056)
- 1241 Tilston (Loc. 09-1241)
- 2186 Grove (Loc. 09-2186)
- 1090 Rankin (Loc. 09-1090)
- 1181 Askin (Loc. 09-1181)
- 1301 Rankin (Loc. 09-1301)
- 1275 Rankin (Loc. 09-1275)
- 2300 Girardot (Loc. 09-2300)
- 1291 Rankin (Loc. 09-1291)
- 1277 Tilston (Loc. 09-1277)
- 981 Merritt (Loc. 09-981)
- 972 Rankin (Loc. 09-972)
- 2241 Girardot (Loc. 09-2241)
- 1287 Askin (Loc. 09-1287)

A list of all areas, including tenant units, assessed as part of this assessment are included in Appendix II – Inventory of Identified Designated Substances and detailed in Appendix I – Survey Drawings.

3.0 SUMMARY OF FINDINGS

An inventory of Identified Designated Substances including a general description of the quantity and nature of the designated substances identified in each location within the facility is provided in Appendix II. This appendix shows the location (Unit number); building system (floor, ceiling, etc.); name of the asbestos-containing material (ACM) such as vinyl floor tiles, ceiling tiles etc.; material description, and quantity; designated substance (asbestos, lead, mercury etc.); condition, and priority for removal, repair or monitoring. A summary of the confirmed/assumed designated substances (DS) identified in 17 of the 72 residential units inspected as part of this assessment is provided in Table 1. Confirmed/assumed DS are summarized based on investigation, observations, sampling, and/or experience. A summary of possible ACM that may be present within the development that could not be confirmed at the time of assessment, based on site conditions, age of construction, etc. is provided in Table 2. Additional investigation and sampling may be required prior to work in locations where possible ACM may be present.

TABLE 1 Summary of Designated Substances Confirmed by Assessment/Sampling Bridgeview I (Various Addresses) – District #2	
Material	Findings
Asbestos	<p>Confirmed asbestos-containing materials (ACM) were identified in the development as follows:</p> <ul style="list-style-type: none"> • Heat Shield Around Ducts & Air Vents (<i>Friable</i>) – ~22 SF observed in 7/17 units. Total estimated quantity (data extrapolated) ~95 SF; • Vinyl Floor Tiles (<i>Non-Friable</i>): <ul style="list-style-type: none"> ○ VFT1 - 12"x12" Beige with Black Veins – ~200 SF observed in 1/17 units. Total estimated quantity (data extrapolated) ~850 SF; ○ VFT3 - 9"x9" Black with Light Brown Streaks – ~40 SF observed in 1/17 units. Total estimated quantity (data extrapolated) ~170 SF.
Lead	<p>Lead-based paints (i.e. concentration of lead equal to or greater than 0.5% or 5000 parts per million (ppm)) were identified in the Project Area as follows:</p> <ul style="list-style-type: none"> • Grey Floor Paint in the Basement areas of tenant units (9200 ppm), this material may be concealed under other flooring materials or other paint colours. <p>No other major sources of lead or lead-containing products were identified during the assessment; however, lead may be present in:</p> <ul style="list-style-type: none"> • Ceramic tiles, • Wiring connectors and electric cable sheathing, and • Piping and solder joints/bell-and-spigot joints on piping.
Mercury	Mercury was NOT observed within thermostats throughout the facility. Minor quantities are present as a vapour within fluorescent tubes lights and as a possible constituent of paints and adhesives.
Silica	Present in all concrete and masonry products.
Other Designated Substances	Acrylonitrile, Arsenic, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, and Vinyl Chloride Monomer were not noted in significant quantities or forms, if at all.

<p>TABLE 2</p> <p>Summary of Possible Asbestos-Containing Materials Within the Facility/Development</p> <p>Glengarry Court Townhomes (Various Addresses), Windsor – District #2</p>	
Material	Findings
Asbestos	<p>Possible ACM that may be present in the facility include but are not limited to:</p> <ul style="list-style-type: none"> • Components or wiring within motors or lights (<i>Non-Friable</i>); • Fire doors (<i>Non-Friable</i>); • High voltage wiring (<i>Non-Friable</i>); • Mechanical packing, ropes and gaskets (<i>Non-Friable</i>); • Other caulking, mastics, adhesives (<i>Non-Friable</i>); • Roofing materials (<i>Non-Friable</i>); • Window caulking (<i>Non-Friable</i>); • Other materials that could not be observed or assessed due to the limitations of this assessment (i.e. intrusive investigation was NOT undertaken during this assessment).

Further findings are presented in attached Appendices, as follows:

- Appendix I – Survey Drawings, depicting the location of presumed and assumed asbestos-containing materials to the extent practicable and room location numbers referenced throughout the report.
- Appendix II – Inventory of Identified Designated Substances, providing a general description of the quantity or nature of the designated substances identified in each location within the facility.
- Appendix III – Observation Report (Photographs), documenting instances of damaged Designated Substances.
- Appendix IV – Results of Bulk Sample Analysis, providing a summary of all bulk samples (asbestos and lead) collected as part of this assessment as well as laboratory chain of custodies and certificates of analyses.

4.0 CONCLUSIONS AND RECOMMENDATIONS

General recommendations for compliance with applicable regulations have been provided in the overview document, “Designated Substances Assessment Scope of Work and Methodology Report”, dated July 2016, prepared by ECOH. The following details are specific recommendations for the facility. Refer to Appendix III – Observation Report for additional information and photographs of damaged/exposed designated substances detailed in the Table 3 (below).

TABLE 3

Recommendations for Corrective Actions

Location Number	Location Name	Hazard	Material/Quantity/Location	Recommended Action	Priority	Abatement Cost Estimate*	Photo # (Appendix III)
09-1339-01	1339 Rankin Basement	Asbestos	1 SF of leftover heat shield residue	REMOVE (Type 2)	PRIORITY 1	\$1,500.00	Photo 10
09-1181-01	1181 Askin Basement	Asbestos	1 SF of leftover heat shield residue	REMOVE (Type 2)	PRIORITY 1	\$1,500.00	Photo 11
09-2300-01	2300 Girardot Basement	Asbestos	2 SF of leftover heat shield residue around vents	REMOVE (Type 2)	PRIORITY 1	\$1,500.00	Photo 12
*Abatement Cost Estimates include Abatement Contractor costs (removal only) and Consulting fees (abatement inspections) and are provided for reference only and may differ significantly depending on tender parameters.							

- All other designated substances identified during this assessment are present in GOOD condition and no other immediate action is required.
- As asbestos is confirmed to be present within the facility, an Asbestos Management Plan (AMP) should be implemented.
- In compliance with Ontario Occupational Health and Safety Act s.30, prior to future construction or renovation projects, additional assessments should be considered to confirm the presence of designated substances that have been assumed to be on-site and/or that may be present in concealed areas (such as above solid ceilings, within bulkheads, pipe chases, etc.).

5.0 LIMITATIONS OF ASSESSMENT

Due to the nature of building construction and on-going building activities, some limitations exist as to the possible thoroughness of a building survey. The field observations, measurements and analysis are considered sufficient in detail and scope to form a reasonable basis for the findings and conclusions presented in this report. The findings and conclusions drawn by ECOH Management Inc. (ECOH) are limited to the specific scope of work for which ECOH was retained and are based solely on information generated as a result of the specific scope of work authorized by Windsor Essex Community Housing Corporation (CHC). The results of the assessment are limited to visual inspection of areas made accessible to ECOH personnel and information obtained from facility personnel, when obtained.

ECOH warrants that the findings and conclusions contained herein have been made in accordance with generally accepted evaluation methods in the industry and applicable regulations at the time of the performance of the assessment. However, there is no warranty, expressed or implied, that this assessment has uncovered all environmental concerns on the subject site. In addition, ECOH cannot guarantee the completeness or accuracy of information supplied by a third party.

This report was prepared by ECOH for Windsor Essex Community Housing Corporation. The material in it reflects ECOH's professional interpretation of information available at the time of report preparation. Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. ECOH accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report. Should additional information become available that suggests other environmental issues of concern beyond that described in this report, ECOH retains the right to review this information and modify conclusions and recommendations presented in this report accordingly.

6.0 CLOSURE

Should there be any questions regarding the contents of this report, please contact the undersigned at 905-795-2800.

ECOH

Environmental Consulting
Occupational Health

Prepared by:



Mahir Bholat, B.Sc.
Environmental Scientist

Reviewed by:




Brian Edwardson, M.S., B.Sc.(Env.)
Senior Project Manager

Reviewed by:



Dr. Om Malik, P.Eng., CIH, ROH, FAIHA, QP
Principal & CEO

APPENDIX I
SURVEY DRAWINGS



Legend

01

Residence Location Numbers

01a

Positive Asbestos Bulk Sample Location
(16313-09-xx)

01a

Negative Asbestos Bulk Sample Location
(16313-09-xx)

Pb-01

Lead Bulk Sample Location
(16313-09-Pb-xx)

Pb-01

Positive Lead Bulk Sample Location
(16313-09-Pb-xx)

Friable Asbestos-Containing Paper Heat Shield

Non-Friable Asbestos-Containing Vinyl Floor Tile

Not Assessed by ECOH

All information relating to room size and location is approximate and for visual aid only. ECOH does not guarantee the drawing to be complete, absolute, accurate or current. The drawing should not be used by any party in lieu of obtaining architectural drawings.

Figure 1

Site Plan

LOCATION:

Bridgeview I (District 2),
Windsor, Ontario

PROJECT:

Designated Substances Survey

CLIENT:

Windsor Essex Community Housing Corporation

PROJECT NUMBER:

16313-09

DATE:

April 2016

DRW BY:

CB

CAD FILE:


FIG1 P16313-09 Bridgeview I

SCALE:

Not to Scale

CHK BY:

SG

 **ECOH**
Environmental Consulting
Occupational Health

APPENDIX II
INVENTORY OF IDENTIFIED DESIGNATED SUBSTANCES

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1014-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1014-01	Basement	Duct	Heat Shield	Asbestos	Visually Consistent with 16313-09-ASB-09	60% Chrysotile	2 SF	G	C	Y	3		Around vents
09-1014-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1014-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-02	Kitchen	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks (under stick-on tiles)
09-1014-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-03	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	Visually Confirmed to be Non-Asbestos	-	-	-	-	-	-	Vinyl Sheet Flooring 3 - Grey, new, no paper backing
09-1014-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-04	Hallway	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks (under stick-on tiles)
09-1014-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-09	Hallway (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-09	Hallway (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1014-10	Attic	No ACM Observed											

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1339-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1339-01	Basement	Duct	Heat Shield	Asbestos	Visually Consistent with 16313-09-ASB-09	60% Chrysotile	1 SF	P	C	Y	1		Leftover residue (Appendix III Photo 10)
09-1339-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1339-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	16313-09-ASB-04C	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-1339-02	Kitchen	Floor	VFT Mastic	Asbestos	16313-09-ASB-04C	None Detected	-	-	-	-	-	-	
09-1339-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	16313-09-ASB-05A-05C	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern
09-1339-03	Washroom	Floor	VSF Mastic	Asbestos	16313-09-ASB-05A-05C	None Detected	-	-	-	-	-	-	
09-1339-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-07	Bedroom #2	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-07	Bedroom #2	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1339-08	Attic	No ACM Observed											
09-1056-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1056-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1056-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-02	Kitchen	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks
09-1056-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stony Pattern
09-1056-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-04	Hallway	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks
09-1056-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-07	Bedroom #2	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-07	Bedroom #2	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1056-08	Attic	No ACM Observed											
09-1241-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1241-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1241-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-1241-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-03	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	Visually Confirmed to be Non-Asbestos	-	-	-	-	-	-	Vinyl Sheet Flooring 3 - Grey, new, no paper backing

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1241-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-1241-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-07	Bedroom #2	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-07	Bedroom #2	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1241-08	Attic	No ACM Observed											
09-2186-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-2186-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-2186-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2186-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern
09-2186-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2186-05	Living Room	Walls	Plaster	Asbestos	16313-09-ASB-08A	None Detected	-	-	-	-	-	-	
09-2186-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-2186-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-06	Bedroom #1	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2186-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-07	Bedroom #2 (2nd Floor)	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2186-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-08	Bedroom #3 (2nd Floor)	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2186-09	Hallway (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-09	Hallway (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2186-09	Hallway (2nd Floor)	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2186-10	Attic	No ACM Observed											
09-1090	No Access												Tenant would not allow us in
09-1181-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1181-01	Basement	Duct	Heat Shield	Asbestos	Visually Consistent with 16313-09-ASB-09	60% Chrysotile	1 SF	P	C	Y	1		Leftover residue (Appendix III Photo 11)
09-1181-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1181-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-1181-03	Washroom	Walls	Plaster	Asbestos	16313-09-ASB-08D	None Detected	-	-	-	-	-	-	
09-1181-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1181-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-1181-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-09	Hallway (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-09	Hallway (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1181-10	Attic	No ACM Observed											
09-1301-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1301-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1301-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	16313-09-ASB-04A	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks (under laminate)
09-1301-02	Kitchen	Floor	VFT Mastic	Asbestos	16313-09-ASB-04A	None Detected	-	-	-	-	-	-	
09-1301-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern (under stick-on tiles)

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1301-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks (under laminate)
09-1301-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	16313-09-ASB-08E	None Detected	-	-	-	-	-	-	
09-1301-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-09	Hallway (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-09	Hallway (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1301-10	Attic	No ACM Observed											
09-1306-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1306-01	Basement	Duct	Heat Shield	Asbestos	16313-09-ASB-09A - 09C	60% Chrysotile	8 SF	G	C	Y	3		Around Vents
09-1306-01	Basement	Floor	Vinyl Floor Tile 3	Asbestos	16313-09-ASB-03A - 03C	2% Chrysotile	40 SF	G	A	N	3	-	Vinyl Floor Tile 3 - 9"x9" Black with Light Brown Streaks
09-1306-01	Basement	Floor	VFT Mastic	Asbestos	16313-09-ASB-03C	None Detected	-	-	-	-	-	-	
09-1306-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1306-02	Kitchen	Walls	Plaster	Asbestos	16313-09-ASB-08F	None Detected	-	-	-	-	-	-	
09-1306-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-02	Kitchen	Floor	Vinyl Floor Tile 2	Asbestos	16313-09-ASB-02A - 02C	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks
09-1306-02	Kitchen	Floor	VFT Mastic	Asbestos	16313-09-ASB-02A - 02C	None Detected	-	-	-	-	-	-	

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1306-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-03	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	Visually Confirmed to be Non-Asbestos	-	-	-	-	-	-	Vinyl Sheet Flooring 1 - Square Pattern, new, no paper backing
09-1306-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-07	Bedroom #2	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-07	Bedroom #2	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-08	Bedroom #3	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-08	Bedroom #3	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1306-09	Attic	No ACM Observed											
09-1275-01	Basement	Walls	Drywall Joint Compound	Asbestos	16313-09-ASB-06C	None Detected	-	-	-	-	-	-	In stairwell
09-1275-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1275-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-02	Kitchen	Floor	Vinyl Floor Tile 1	Asbestos	16313-09-ASB-01A	2% Chrysotile	100 SF	G	A	N	3	-	Vinyl Floor Tile 1 - 12"x12" Beige with Black Veins
09-1275-02	Kitchen	Floor	VFT Mastic	Asbestos	16313-09-ASB-01A	None Detected	-	-	-	-	-	-	
09-1275-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-03	Washroom	Floor	Vinyl Floor Tile 1	Asbestos	16313-09-ASB-01B	2% Chrysotile	40 SF	G	A	N	3	-	Vinyl Floor Tile 1 - 12"x12" Beige with Black Veins
09-1275-02	Washroom	Floor	VFT Mastic	Asbestos	16313-09-ASB-01B	None Detected	-	-	-	-	-	-	

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1275-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-04	Hallway	Floor	Vinyl Floor Tile 1	Asbestos	16313-09-ASB-01C	2% Chrysotile	60 SF	G	A	N	3	-	Vinyl Floor Tile 1 - 12"x12" Beige with Black Veins
09-1275-04	Hallway	Floor	VFT Mastic	Asbestos	16313-09-ASB-01C	None Detected	-	-	-	-	-	-	
09-1275-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	16313-09-ASB-08G	None Detected	-	-	-	-	-	-	
09-1275-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1275-10	Attic	No ACM Observed											
09-2300-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-2300-01	Basement	Duct	Heat Shield	Asbestos	Visually Consistent with 16313-09-ASB-09	60% Chrysotile	2 SF	P	C	Y	1	-	Residue around vents (Appendix III Photo 12)
09-2300-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-2300-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2300-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-2300-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2300-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2300-10	Attic	No ACM Observed											
09-1291-01	Basement	Walls	Drywall Joint Compound	Asbestos	16313-09-ASB-06A - 06B	None Detected	-	-	-	-	-	-	In stairwell
09-1291-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1291-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks (under laminate)
09-1291-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern (under stick-on tiles)

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1291-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	16313-09-ASB-04B	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks (under laminate)
09-1291-04	Hallway	Floor	VFT Mastic	Asbestos	16313-09-ASB-04B	None Detected	-	-	-	-	-	-	
09-1291-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-05	Living Room	Ceiling	Ceiling Texture Finish	Asbestos	16313-09-ASB-07A - 07C	None Detected	-	-	-	-	-	-	
09-1291-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1291-10	Attic	No ACM Observed											
09-1277-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1277-01	Basement	Duct	Heat Shield	Asbestos	Visually Consistent with 16313-09-ASB-09	60% Chrysotile	5 SF	G	C	Y	3		Around Vents
09-1277-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1277-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-02	Kitchen	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks (under stick-on tiles)

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1277-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-03	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	Visually Confirmed to be Non-Asbestos	-	-	-	-	-	-	Vinyl Sheet Flooring 1 - Square Pattern, new, no paper backing
09-1277-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-04	Hallway	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks (under stick-on tiles)
09-1277-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-06	Bedroom #1	Walls	Plaster	Asbestos	16313-09-ASB-08B	None Detected	-	-	-	-	-	-	
09-1277-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1277-10	Attic	No ACM Observed											
09-981-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-981-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-981-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-981-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern (under stick-on tiles)
09-981-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-981-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-981-10	Attic	No ACM Observed											
09-972-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-972-01	Basement	Duct	Heat Shield	Asbestos	Visually Consistent with 16313-09-ASB-09	60% Chrysotile	3 SF	G	C	Y	3		Around Vents
09-972-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-972-02	Kitchen	Walls	Plaster	Asbestos	16313-09-ASB-08C	None Detected	-	-	-	-	-	-	
09-972-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-02	Kitchen	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks (under laminate)

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-972-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-03	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	Visually Confirmed to be Non-Asbestos	-	-	-	-	-	-	Vinyl Sheet Flooring 3 - Grey, new, no paper backing
09-972-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-04	Hallway	Floor	Vinyl Floor Tile 2	Asbestos	Visually Consistent with 16313-09-ASB-02	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 2 - 12"x12" Beige with Dark Streaks (under laminate)
09-972-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-972-10	Attic	No ACM Observed											
09-2241-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-2241-01	Basement	Floor	Grey Paint	Lead	Visually Consistent with 16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-2241-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-2241-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-03	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Visually Consistent with 16313-09-ASB-05	None Detected	-	-	-	-	-	-	Vinyl Sheet Flooring 2 - Beige with Stoney Pattern
09-2241-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-04	Hallway	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-2241-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-07	Bedroom #2 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-07	Bedroom #2 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-08	Bedroom #3 (2nd Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-08	Bedroom #3 (2nd Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-09	Hallway (Second Floor)	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-09	Hallway (Second Floor)	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-2241-10	Attic	No ACM Observed											

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
09-1287-01	Basement	Walls	Drywall Joint Compound	Asbestos	Visually Consistent with 16313-09-ASB-06	None Detected	-	-	-	-	-	-	In stairwell
09-1287-01	Basement	Floor	Grey Paint	Lead	16313-09-PB-01	9200 ppm	600 SF	G	A	-	-	-	
09-1287-02	Kitchen	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-02	Kitchen	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-02	Kitchen	Floor	Vinyl Floor Tile 4	Asbestos	Visually Consistent with 16313-09-ASB-04	None Detected	-	-	-	-	-	-	Vinyl Floor Tile 4 - 12"x12" Beige with Brown Marks
09-1287-03	Washroom	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-03	Washroom	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-03	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	Visually Confirmed to be Non-Asbestos	-	-	-	-	-	-	Vinyl Sheet Flooring 3 - Grey, new, no paper backing
09-1287-04	Hallway	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-04	Hallway	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-05	Living Room	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-05	Living Room	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-06	Bedroom #1	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-06	Bedroom #1	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-07	Bedroom #2	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-07	Bedroom #2	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-08	Bedroom #3	Walls	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-08	Bedroom #3	Ceiling	Plaster	Asbestos	Visually Consistent with 16313-09-ASB-08	None Detected	-	-	-	-	-	-	
09-1287-09	Attic	No ACM Observed											

Project Number:	16313-09	Date(s) of Current Survey:	April 11, 2016
Building Name:	Bridgeview I – District #2	Organization Completing Survey:	ECOH
Building Address:	Various Addresses, Windsor, Ontario	Facility Coordinator:	

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Access	Friable (Y/N)	Abatement Priority	Abatement Cost Estimate	Notes or Other Observations
Notes													
Additional Asbestos Containing Materials (ACM) may be present within concealed locations throughout the facility (i.e. above solid ceilings, within walls, pipe chases, etc.) or presumed to be present in various building components as detailed in the "Designated Substances Scope of Work and Methodology Report, dated July 2016, prepared by ECOH.													
Lead-based paints (i.e. concentrations of lead equal to or greater than 0.5%) were identified during the assessment within the Basement Floor Paint (Grey).													
Mercury may be present throughout the facility in minor quantities as vapour within fluorescent light tubes and as a possible constituent of paints and adhesives.													
Silica is present in all concrete and masonry products.													

Access

- Access A:** Common areas of the building within reach of all building users (up to approximately 8'-9' from floor level). Includes areas where occupant activities may result in disturbance of the material that is not normally within reach from floor level, but may be easily disturbed by common activities (e.g. games rooms, public storage areas, laundry, etc.). Describes a material that can easily be disturbed.
- Access B:** Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and materials within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines and accessible pipe chases.
- Access C:** Areas of the building above 8' 9' from floor level where use of a ladder is required to reach the material. Includes materials that are not visible and require the removal of a building component to access and view, such as ceiling tiles, access panels and hatches. Includes rarely entered crawl spaces, attic spaces, etc. Observations limited to the extent visible from the access points.
- Access D:** Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc., where demolition of the ceiling, wall or equipment etc. is required to view the material. Evaluation of condition and extent of ACM limited or impossible, depending on the surveyor's ability to visually examine materials.

APPENDIX III
OBSERVATION REPORT



Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 1.

Date:
April 11, 2016

Location:
1275 Rankin Attic
(Loc. 09-1275-10)

Description:
Non-asbestos attic
insulation



Photo No. 2.

Date:
April 11, 2016


Location:
1275 Rankin Kitchen
(Loc. 09-1275-02)

Description:
Asbestos-containing Vinyl
Floor Tile 1 (VFT1) –
12”x12” Beige with Black
Veins.




Client Name: Windsor Essex Community Housing Corporation (CHC)	Site Location: Various Addresses , Windsor, Ontario Bridgeview I (Various Addresses) – District #2	Project No. 16313-09
--	---	--------------------------------

Photo No. 3.	
Date: April 11, 2016	
Location: 1306 Rankin Kitchen (Loc. 09-1306-02)	
Description: Non-asbestos Vinyl Floor Tile 2 (VFT2) – 12”x12” Beige with Dark Streaks	

Photo No. 4.	
Date: April 11, 2016	
Location: 1306 Rankin Basement (Loc. 09-1306-01)	
Description: Asbestos-containing Vinyl Floor Tile 3 (VFT3) – 9”x 9” Black with Light Brown Streaks	

Client Name: Windsor Essex Community Housing Corporation (CHC)	Site Location: Various Addresses , Windsor, Ontario Bridgeview I (Various Addresses) – District #2	Project No. 16313-09
--	---	--------------------------------

Photo No. 5.	
Date: April 11, 2016	
Location: 1306 Rankin Washroom (Loc. 09-1306-03)	
Description: Non-asbestos Vinyl Sheet Floor 1 (VSF1) – Square Pattern	

Photo No. 6.	
Date: April 11, 2016	
Location: 1339 Rankin Washroom (Loc. 09-1339-03)	
Description: Non-asbestos Vinyl Sheet Floor 2 (VSF2) – Beige with Stoney Pattern	



Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 7.

Date:
April 11, 2016

Location:
1291 Rankin Hallway
(Loc. 09-1291-04)

Description:
Non-asbestos Vinyl Floor
Tile 4 (VFT4) – 12"x12"
Beige with Brown Marks



Photo No. 8.

Date:
April 11, 2016

Location:
1014 Rankin
(Loc. 09-1014-03)

Description:
Non-asbestos Vinyl
Sheet Floor 3 (VSF3) –
Grey





Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 9.

Date:
April 11, 2016

Location:
1291 Rankin Living
Room
(Loc. 09-1291-05)

Description:
Non-asbestos texture
finish on plaster



Photo No. 10.

Date:
April 11, 2016

Location:
1339 Rankin
Basement
(Loc. 09-1339-01)

Description:
Asbestos-containing
Heat Shield residue
observed in POOR
condition





Client Name:
Windsor Essex Community Housing
Corporation (CHC)

Site Location:
Various Addresses , Windsor, Ontario
Bridgeview I (Various Addresses) – District #2

Project No.
16313-09

Photo No. 11.

Date:
April 11, 2016

Location:
1181 Askin Basement
(Loc. 09-1181-01)

Description:
Asbestos-containing
Heat Shield residue
observed in POOR
condition



Photo No. 12.

Date:
April 11, 2016

Location:
2300 Girardot
Basement
(Loc. 09-2300-01)

Description:
Asbestos-containing
Heat Shield around
vents observed in
POOR condition



APPENDIX IV
RESULTS OF BULK SAMPLE ANALYSIS FOR ASBESTOS AND LEAD

TABLE 4 Summary of Analysis – Asbestos Bulk Samples Collected					
Sample Number	Sample Location	Sample Description	Results	Photo Number	Figure
16313-09-ASB-01A	1275 Rankin Kitchen (Loc. 09-1275-02)	VFT 1 – 12”x12” Beige with Black Veins	2% Chrysotile	2	1
		VFT 1 Black Mastic	None Detected	N/A	1
16313-09-ASB-01B	1275 Rankin Washroom (Loc. 09-1275-03)	VFT 1 – 12”x12” Beige with Black Veins	Stop Positive (Not Analyzed)	N/A	1
		VFT 1 Black Mastic	None Detected	N/A	1
16313-09-ASB-01C	1275 Rankin Hallway (Loc. 09-1275-04)	VFT 1 – 12”x12” Beige with Black Veins	Stop Positive (Not Analyzed)	N/A	1
		VFT 1 Black Mastic	None Detected	N/A	1
16313-09-ASB-02A	1306 Rankin Kitchen (Loc. 09-1306-02)	VFT 2 – 12”x12” Beige with Dark Streaks	None Detected	3	1
		VFT 2 Brown Mastic	None Detected	N/A	1
16313-09-ASB-02B	1306 Rankin Kitchen (Loc. 09-1306-02)	VFT 2 – 12”x12” Beige with Dark Streaks	None Detected	N/A	1
		VFT 2 Brown Mastic	None Detected	N/A	1
16313-09-ASB-02C	1306 Rankin Kitchen (Loc. 09-1306-02)	VFT 2 – 12”x12” Beige with Dark Streaks	None Detected	N/A	1
		VFT 2 Black Mastic	None Detected	N/A	1
16313-09-ASB-03A	1306 Rankin Basement (Loc. 09-1306-01)	VFT 3 – 9”x9” Black with Light Brown Streaks	2% Chrysotile	4	1
16313-09-ASB-03B	1306 Rankin Basement (Loc. 09-1306-01)	VFT 3 – 9”x9” Black with Light Brown Streaks	Stop Positive (Not Analyzed)	N/A	1

TABLE 4 Summary of Analysis – Asbestos Bulk Samples Collected					
Sample Number	Sample Location	Sample Description	Results	Photo Number	Figure
16313-09-ASB-03C	1306 Rankin Basement (Loc. 09-1306-01)	VFT 3 – 9”x9” Black with Light Brown Streaks	Stop Positive (Not Analyzed)	N/A	1
		VFT 3 Black Mastic	None Detected	N/A	1
16313-09-ASB-04A	1301 Rankin Kitchen (Loc. 09-1301-02)	VFT 4 – 12”x12” Beige with Brown Marks	None Detected	7	1
		VFT 4 Black Mastic	None Detected	N/A	1
16313-09-ASB-04B	1291 Rankin Hallway (Loc. 09-1291-04)	VFT 4 – 12”x12” Beige with Brown Marks	None Detected	N/A	1
		VFT 4 Black Mastic	None Detected	N/A	1
16313-09-ASB-04C	1339 Rankin Kitchen (Loc. 09-1339-02)	VFT 4 – 12”x12” Beige with Brown Marks	None Detected	N/A	1
		VFT 4 Black Mastic	None Detected	N/A	1
16313-09-ASB-05A	1339 Rankin Washroom (Loc. 09-1339-03)	VSF 2 – Beige with Stoney Pattern	None Detected	6	1
16313-09-ASB-05B	1339 Rankin Washroom (Loc. 09-1339-03)	VSF 2 – Beige with Stoney Pattern	None Detected	N/A	1
16313-09-ASB-05C	1339 Rankin Washroom (Loc. 09-1339-03)	VSF 2 – Beige with Stoney Pattern	None Detected	N/A	1
		VSF 2 – Yellow Mastic	None Detected	N/A	1
16313-09-ASB-06A	1291 Rankin Basement (Loc. 09-1291-01)	Drywall Joint Compound	None Detected	N/A	1
16313-09-ASB-06B	1291 Rankin Basement (Loc. 09-1291-01)	Drywall Joint Compound	None Detected	N/A	1

TABLE 4 Summary of Analysis – Asbestos Bulk Samples Collected					
Sample Number	Sample Location	Sample Description	Results	Photo Number	Figure
16313-09-ASB-06C	1275 Rankin Basement (Loc. 09-1275-01)	Drywall Joint Compound	None Detected	N/A	1
16313-09-ASB-07A	1291 Rankin Living Room (Loc. 09-1291-05)	Texture Finish on Plaster	None Detected	9	1
16313-09-ASB-07B	1291 Rankin Living Room (Loc. 09-1291-05)	Texture Finish on Plaster	None Detected	N/A	1
16313-09-ASB-07C	1291 Rankin Living Room (Loc. 09-1291-05)	Texture Finish on Plaster	None Detected	N/A	1
16313-09-ASB-08A	2186 Grove Living Room (Loc. 09-2186-05)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1
16313-09-ASB-08B	1277 Tilston Bedroom (Loc. 09-1277-06)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1
16313-09-ASB-08C	972 Rankin Kitchen (Loc. 09-972-02)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1
16313-09-ASB-08D	1181 Askin Washroom (Loc. 09-1181-03)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1
16313-09-ASB-08E	1301 Rankin Bedroom (Loc. 09-1301-08)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1
16313-09-ASB-08F	1306 Rankin Kitchen (Loc. 09-1306-02)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1

TABLE 4 Summary of Analysis – Asbestos Bulk Samples Collected					
Sample Number	Sample Location	Sample Description	Results	Photo Number	Figure
16313-09-ASB-08G	1275 Rankin Bedroom (Loc. 09-1306-07)	Plaster – Skim Coat	None Detected	N/A	1
		Plaster – Rough Coat	None Detected	N/A	1
16313-09-ASB-09A	1306 Rankin Basement (Loc. 09-1306-01)	Paper Heat Shield	60% Chrysotile	N/A	1
16313-09-ASB-09B	1306 Rankin Basement (Loc. 09-1306-01)	Paper Heat Shield	Stop Positive (Not Analyzed)	N/A	1
16313-09-ASB-09C	1306 Rankin Basement (Loc. 09-1306-01)	Paper Heat Shield	Stop Positive (Not Analyzed)	N/A	1
	- Shading indicates sample result positive for asbestos (if applicable)				
VFT=Vinyl Floor Tile; CT=Ceiling Tile; VSF=Vinyl Sheet Flooring					



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L9T 5N4

Tel/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order: 551604362

Customer ID: 55ECOH45

Customer PO: 16313-09

Project ID:

Attention: Steve Gore
ECOH Management, Inc.
75 Courtneypark Drive West
Unit 1
Mississauga, ON L5W 0E3
Project: 16313-09 BRIDGEVIEW I

Phone: (905) 795-2800
Fax: (905) 795-2870
Received Date: 04/18/2016 4:37 PM
Analysis Date: 04/25/2016
Collected Date:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
16313-09-ASB-01A-Flo or Tile 551604362-0001	Vinyl Floor Tile 1 (VFT-1)-12"x12" Beige w/Black Veins-1275 Rankin	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
16313-09-ASB-01A-Mas tic 551604362-0001A	Vinyl Floor Tile 1 (VFT-1)-12"x12" Beige w/Black Veins-1275 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-01B-Flo or Tile 551604362-0002	Vinyl Floor Tile 1 (VFT-1)-12"x12" Beige w/Black Veins-1275 Rankin				Positive Stop (Not Analyzed)
16313-09-ASB-01B-Mas tic 551604362-0002A	Vinyl Floor Tile 1 (VFT-1)-12"x12" Beige w/Black Veins-1275 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-01C-Flo or Tile 551604362-0003	Vinyl Floor Tile 1 (VFT-1)-12"x12" Beige w/Black Veins-1275 Rankin				Positive Stop (Not Analyzed)
16313-09-ASB-01C-Ma stic 551604362-0003A	Vinyl Floor Tile 1 (VFT-1)-12"x12" Beige w/Black Veins-1275 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-02A-Flo or Tile 551604362-0004	Vinyl Floor Tile 2 (VFT-2)-12"x12" Beige w/Dark Streaks- 1306 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-02A-Mas tic 551604362-0004A	Vinyl Floor Tile 2 (VFT-2)-12"x12" Beige w/Dark Streaks- 1306 Rankin	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-02B-Flo or Tile 551604362-0005	Vinyl Floor Tile 2 (VFT-2)-12"x12" Beige w/Dark Streaks- 1306 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-02B-Mas tic 551604362-0005A	Vinyl Floor Tile 2 (VFT-2)-12"x12" Beige w/Dark Streaks- 1306 Rankin	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-02C-Flo or Tile 551604362-0006	Vinyl Floor Tile 2 (VFT-2)-12"x12" Beige w/Dark Streaks -1306 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-02C-Ma stic 551604362-0006A	Vinyl Floor Tile 2 (VFT-2)-12"x12" Beige w/Dark Streaks -1306 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial Report From: 04/25/2016 17:50:52



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L9T 5N4

Tel/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order: 551604362

Customer ID: 55ECOH45

Customer PO: 16313-09

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
16313-09-ASB-03A 551604362-0007 <i>No mastic present</i>	Vinyl Floor Tile 3 (VFT-3)-9"x9" Black w/Light Brown Streaks -1306 Rankin	Black Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
16313-09-ASB-03B 551604362-0008 <i>no mastic present</i>	Vinyl Floor Tile 3 (VFT-3)-9"x9" Black w/Light Brown Streaks -1306 Rankin				Positive Stop (Not Analyzed)
16313-09-ASB-03C-Flo or Tile 551604362-0009	Vinyl Floor Tile 3 (VFT-3)-9"x9" Black w/Light Brown Streaks- 1306 Rankin				Positive Stop (Not Analyzed)
16313-09-ASB-03C-Ma stic 551604362-0009A	Vinyl Floor Tile 3 (VFT-3)-9"x9" Black w/Light Brown Streaks- 1306 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-04A-Flo or Tile 551604362-0010	Vinyl Floor Tile 4 (VFT-4)-12"x12" Beige w/Brown Marks-1301 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-04A-Mas tic 551604362-0010A	Vinyl Floor Tile 4 (VFT-4)-12"x12" Beige w/Brown Marks-1301 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-04B-Flo or Tile 551604362-0011	Vinyl Floor Tile 4 (VFT-4)-12"x12" Beige w/Brown Marks- 1291 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-04B-Mas tic 551604362-0011A	Vinyl Floor Tile 4 (VFT-4)-12"x12" Beige w/Brown Marks- 1291 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-04C-Flo or Tile 551604362-0012	Vinyl Floor Tile 4 (VFT-4)-12"x12" Beige w/Brown Marks- 1339 Rankin	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-04C-Ma stic 551604362-0012A	Vinyl Floor Tile 4 (VFT-4)-12"x12" Beige w/Brown Marks- 1339 Rankin	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-05A 551604362-0013 <i>insufficient mastic</i>	Vinyl Sheet Flooring 2 (VSF-2) Beige w/Stoney Pattern-1339 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-05B 551604362-0014 <i>insufficient mastic</i>	Vinyl Sheet Flooring 2 (VSF-2) Beige w/Stoney Pattern-1339 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-05C-Vin yl Sheet Flooring 551604362-0015	Vinyl Sheet Flooring 2 (VSF-2) Beige w/Stoney Pattern-1339 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial Report From: 04/25/2016 17:50:52



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L9T 5N4

Tel/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order: 551604362

Customer ID: 55ECOH45

Customer PO: 16313-09

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
16313-09-ASB-05C-Mastic 551604362-0015A	Vinyl Sheet Flooring 2 (VSF-2) Beige w/Stoney Pattern-1339 Rankin	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-06A 551604362-0016	Drywall Joint Compound-1291 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-06B 551604362-0017	Drywall Joint Compound-1291 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-06C 551604362-0018	Drywall Joint Compound-1275 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-07A 551604362-0019	Texture Finish on Plaster-1291 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-07B 551604362-0020	Texture Finish on Plaster-1291 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-07C 551604362-0021	Texture Finish on Plaster-1291 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08A-Ski m Coat 551604362-0022	Wall Plaster-2186 Grove	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08A-Rough Coat 551604362-0022A	Wall Plaster-2186 Grove	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08B-Ski m Coat 551604362-0023	Wall Plaster-1277 Tilston	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08B-Rough Coat 551604362-0023A	Wall Plaster-1277 Tilston	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08C-Ski m Coat 551604362-0024	Wall Plaster-972 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08C-Rough Coat 551604362-0024A	Wall Plaster-972 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08D-Ski m Coat 551604362-0025	Wall Plaster-1181 Askin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08D-Rough Coat 551604362-0025A	Wall Plaster-1181 Askin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16313-09-ASB-08E-Ski m Coat 551604362-0026	Wall Plaster-1301 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial Report From: 04/25/2016 17:50:52



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L9T 5N4

Tel/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order: 551604362

Customer ID: 55ECOH45

Customer PO: 16313-09

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
16313-09-ASB-08E-Rou gh Coat	Wall Plaster-1301 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
551604362-0026A					
16313-09-ASB-08F-Ski m Coat	Wall Plaster-1306 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
551604362-0027					
16313-09-ASB-08F-Rou gh Coat	Wall Plaster-1306 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
551604362-0027A					
16313-09-ASB-08G-Ski m Coat	Wall Plaster-1275 Rankin	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
551604362-0028					
16313-09-ASB-08G-Ro ugh Coat	Wall Plaster-1275 Rankin	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
551604362-0028A					
16313-09-ASB-09A	Paper Heat Shield-1306 Rankin	Gray Non-Fibrous Homogeneous		40% Non-fibrous (Other)	60% Chrysotile
551604362-0029					
16313-09-ASB-09B	Paper Heat Shield-1306 Rankin				Positive Stop (Not Analyzed)
551604362-0030					
16313-09-ASB-09C	Paper Heat Shield-1306 Rankin				Positive Stop (Not Analyzed)
551604362-0031					

Analyst(s)

John Biesiadecki (27)

Romeo Samson (16)


Matthew Davis
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Initial Report From: 04/25/2016 17:50:52


EMSL CANADA, INC.
 LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

551604362

EMSL CANADA, INC.
 2756 SLOUGH STREET
 MISSISSAUGA, ON L4T 1G3
 PHONE: (289) 997-4602
 FAX: (289) 997-4609

Company: ECOH		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 75 Courtneypark Dr. W., Unit 1		Third Party Billing requires written authorization from third party	
City: Mississauga	State/Province: Ontario	Zip/Postal Code: L5W 0E3	Country: Canada
Report To (Name): Steven Gore, Mahir Bholat, Brian Edw		Fax #: 905-795-2870	
Telephone #: 905.795.2800		Email Address: sgore@ecoh.ca, mbholat@ecoh.ca,	
Project Name/Number: 16313-09		Bridgeview I bedwardson@ecoh.ca	
Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email		Purchase Order: U.S. State Samples Taken:	
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hours <input type="checkbox"/> 6 Hours <input type="checkbox"/> 24 Hrs <input type="checkbox"/> 48 Hrs <input type="checkbox"/> 3 Days <input type="checkbox"/> 4 Days <input checked="" type="checkbox"/> 5 Days <input type="checkbox"/> 10 Days			
*For TEM Air 3 hours/6 hours, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.			
PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA PLM - Bulk (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input checked="" type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravometric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198-1 (friable in NY) <input type="checkbox"/> NYS 198-1 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)		TEM - Air <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec 2.5 TEM - Water: EPA 100.2 Fibres > 10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fibre Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	
		TEM-Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) Other:	
<input checked="" type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group			
Samplers Name: Steven Gore		Samplers Signature:	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
16313-09-ASB- 01A	Vinyl Floor Tile 1 (VFT-1) - 12"x12" Beige with Black Veins - 1275 Rankin		April 11, 2016
16313-09-ASB- 01B	Vinyl Floor Tile 1 (VFT-1) - 12"x12" Beige with Black Veins - 1275 Rankin		April 11, 2016
16313-09-ASB- 01C	Vinyl Floor Tile 1 (VFT-1) - 12"x12" Beige with Black Veins - 1275 Rankin		April 11, 2016
16313-09-ASB- 02A	Vinyl Floor Tile 2 (VFT-2) - 12"x12" Beige with Dark Streaks - 1306 Rankin		April 11, 2016
16313-09-ASB- 02B	Vinyl Floor Tile 2 (VFT-2) - 12"x12" Beige with Dark Streaks - 1306 Rankin		April 11, 2016
16313-09-ASB- 02C	Vinyl Floor Tile 2 (VFT-2) - 12"x12" Beige with Dark Streaks - 1306 Rankin		April 11, 2016
16313-09-ASB- 03A	Vinyl Floor Tile 3 (VFT-3) - 9"x9" Black with Light Brown Streaks - 1306 Rankin		April 11, 2016
16313-09-ASB- 03B	Vinyl Floor Tile 3 (VFT-3) - 9"x9" Black with Light Brown Streaks - 1306 Rankin		April 11, 2016
Client Sample # (s): 16313-09-ASB-01a - 16313-09-ASB-09c		Total # of Samples: 31	
Relinquished (Client): Steven Gore		Date: April 18, 2016 Time:	
Received (Lab):		Date: Time:	
Comments/Special Instructions:			

Wafkin JH



EMSL CANADA, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number *(Lab Use Only):*

EMSL CANADA, INC.
2756 SLOUGH STREET
MISSISSAUGA, ON L4T 1G3
PHONE: (289) 997-4602
FAX: (289) 997-4609

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
16313-09-ASB- 03C	Vinyl Floor Tile 3 (VFT-3) - 9"x9" Black with Light Brown Streaks - 1306 Rankin		April 11, 2016
16313-09-ASB- 04A	Vinyl Floor Tile 4 (VFT-4) - 12"x12" Beige with Brown Marks - 1301 Rankin		April 11, 2016
16313-09-ASB- 04B	Vinyl Floor Tile 4 (VFT-4) - 12"x12" Beige with Brown Marks - 1291 Rankin		April 11, 2016
16313-09-ASB- 04C	Vinyl Floor Tile 4 (VFT-4) - 12"x12" Beige with Brown Marks - 1339 Rankin		April 11, 2016
16313-09-ASB- 05A	Vinyl Sheet Flooring 2 (VSF-2) - Beige with Stoney Pattern - 1339 Rankin		April 11, 2016
16313-09-ASB- 05B	Vinyl Sheet Flooring 2 (VSF-2) - Beige with Stoney Pattern - 1339 Rankin		April 11, 2016
16313-09-ASB- 05C	Vinyl Sheet Flooring 2 (VSF-2) - Beige with Stoney Pattern - 1339 Rankin		April 11, 2016
16313-09-ASB- 06A	Drywall Joint Compound - 1291 Rankin		April 11, 2016
16313-09-ASB- 06B	Drywall Joint Compound - 1291 Rankin		April 11, 2016
16313-09-ASB- 06C	Drywall Joint Compound - 1275 Rankin		April 11, 2016
16313-09-ASB- 07A	Texture Finish on Plaster - 1291 Rankin		April 11, 2016
16313-09-ASB- 07B	Texture Finish on Plaster - 1291 Rankin		April 11, 2016
16313-09-ASB- 07C	Texture Finish on Plaster - 1291 Rankin		April 11, 2016
16313-09-ASB- 08A	Wall Plaster - 2186 Grove		April 11, 2016
16313-09-ASB- 08B	Wall Plaster - 1277 Tilston		April 11, 2016
16313-09-ASB- 08C	Wall Plaster - 972 Rankin		April 11, 2016
16313-09-ASB- 08D	Wall Plaster - 1181 Askin		April 11, 2016
16313-09-ASB- 08E	Wall Plaster - 1301 Rankin		April 11, 2016
16313-09-ASB- 08F	Wall Plaster - 1306 Rankin		April 11, 2016
16313-09-ASB- 08G	Wall Plaster - 1275 Rankin		April 11, 2016
16313-09-ASB- 09A	Paper Heat Shield - 1306 Rankin		April 11, 2016
16313-09-ASB- 09B	Paper Heat Shield - 1306 Rankin		April 11, 2016
16313-09-ASB- 09C	Paper Heat Shield - 1306 Rankin		April 11, 2016

***Comments/Special Instructions:**

TABLE 5 Summary of Analysis – Lead Bulk Samples Collected				
Sample number	Location	Description	Analytical Results (ppm)	Result
16313-09-Pb-01	1287 Askin Basement (Loc. 09-1287-01)	Grey Floor Paint	9,200	POSITIVE
16313-09-Pb-02	1275 Rankin Hallway (Loc. 09-1275-04)	Brown Stairwell Paint	<99	NEGATIVE (LCM)
16313-09-Pb-03	1275 Rankin Hallway (Loc. 09-1275-04)	Beige Wall Paint	2,100	NEGATIVE (LCM)
16313-09-Pb-04	1301 Rankin Kitchen (Loc. 09-1301-02)	Beige Wall Paint	2,100	NEGATIVE (LCM)
16313-09-Pb-05	1306 Rankin Kitchen (Loc. 09-1306-02)	Blue/Beige/Light Green Wall Paint	1,900	NEGATIVE (LCM)
	- Shading indicates sample result positive for lead-based-paint (if applicable)			
LBM=Lead-based Material (i.e. lead content ≥5000ppm); LCM=Lead-containing Material (i.e. lead content <0.5% or 5000ppm)				

**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L9T 5N4

Phone/Fax: 289-997-4602 / (289) 997-4607

<http://www.EMSL.com>torontolab@emsl.com

EMSL Canada Or 551604338

CustomerID: 55ECOH45

CustomerPO: 16313-09

ProjectID:

Attn: **Steve Gore**
ECOH Management, Inc.
75 Courtneypark Drive West
Unit 1
Mississauga, ON L5W 0E3

Phone: (905) 795-2800
Fax: (905) 795-2870
Received: 04/18/16 4:36 PM
Collected:

Project: **16313-09 BRIDGEVIEW I****Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Lead Concentration</i>
16313-09-PB-1	551604338-0001	4/21/2016		9200 ppm
Site: GREY FLOOR PAINT - 1287 ASKIN				
16313-09-PB-2	551604338-0002	4/21/2016		<99 ppm
Site: BROWN STAIRWELL PAINT - 1275 RANKIN				
Insufficient sample to reach reporting limit.				
16313-09-PB-3	551604338-0003	4/21/2016		2100 ppm
Site: BEIGE WALL PAINT - 1275 RANKIN				
16313-09-PB-4	551604338-0004	4/21/2016		2100 ppm
Site: BEIGE WALL PAINT - 1301 RANKIN				
16313-09-PB-5	551604338-0005	4/21/2016		1900 ppm
Site: BLUE/BEIGE/LIGHT GREEN WALL PAINT - 1306 RANKIN				

Shiraz Saloojee
or other approved signatory

*Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.010 % wt based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise.

Samples analyzed by EMSL Canada Inc. Mississauga, ON A2LA Accredited Environmental Testing Cert #2845.08

Initial report from 04/25/2016 10:52:39



EMSL CANADA, INC.
LABORATORY • PRODUCTS • TRAINING

Lead (Pb) Chain of Custody

EMSL Order Number (Lab Use Only):

551604338

EMSL CANADA, INC.
2756 SLOUGH STREET
MISSISSAUGA, ON L4T 1G3
PHONE: (289) 997-4602
FAX: (289) 997-4609

Company: ECOH		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 75 Courtney Park Dr. W., Unit 1		Third Party Billing requires written authorization from third party	
City: Mississauga	State/Province: Ontario	Zip/Postal Code: L5W 0E3	Country: Canada
Steven Gore, Mahir Bholat, Brian Edwardson		Telephone #: 905-795-2800	
sgore@ecoh.ca, mbholat@ecoh.ca, bedwardson@ecoh.ca		Fax #: 905-795-2870	Purchase Order:
Project Name/Number: 16313-09 Bridgeview I		Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email	
U.S. State Samples Taken:		CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt	
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input checked="" type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
*Analysis completed in accordance with EMSL's Terms and Conditions located in the Price Guide			
Matrix	Method	Instrument	Reporting Limit
Chips <input type="checkbox"/> % by wt. <input type="checkbox"/> mg/cm ² <input checked="" type="checkbox"/> ppm	SW846-7000B	Flame Atomic Absorption	0.01%
Air	NIOSH 7082	Flame Atomic Absorption	4 µg/filter
	NIOSH 7105	Graphite Furnace AA	0.03 µg/filter
	NIOSH 7300 modified	ICP-AES/ICP-MS	0.5 µg/filter
Wipe* <input type="checkbox"/> ASTM <input type="checkbox"/> non-ASTM <input type="checkbox"/> *If no box is checked, non-ASTM Wipe is assumed	SW846-7000B	Flame Atomic Absorption	10 µg/wipe
	SW846-6010B or C	ICP-AES	1.0 µg/wipe
TCLP	SW846-1311/7000B/SM 3111B	Flame Atomic Absorption	0.4 mg/L (ppm)
	SW846-1131/SW846-6010B or C	ICP-AES	0.1 mg/L (ppm)
Soil	SW846-7000B	Flame Atomic Absorption	40 mg/kg (ppm)
	SW846-6010B or C	ICP-AES	2 mg/kg (ppm)
Wastewater Unpreserved <input type="checkbox"/> Preserved with HNO ₃ pH <2 <input type="checkbox"/>	SM3111B/SW846-7000B	Flame Atomic Absorption	0.4 mg/L (ppm)
	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)
	EPA200.7	ICP-AES	0.020 mg/L (ppm)
Drinking Water Unpreserved <input type="checkbox"/> Preserved with HNO ₃ pH <2 <input type="checkbox"/>	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)
	EPA 200.8	ICP-MS	0.0031mg/L (ppm)
TSP/SPM Filter	40 CFR Part 50 (2013)	ICP-MS	1.2 µg/filter
Other:			
Name of Sampler: Steven Gore		Signature of Sampler:	
Sample #	Location	Volume/Area	Date/Time Sampled
16313-09-Pb- 1	Grey Floor Paint - 1287 Askin		April 11, 2016
16313-09-Pb- 2	Brown Stairwell Paint - 1275 Rankin		April 11, 2016
16313-09-Pb- 3	Beige Wall Paint - 1275 Rankin		April 11, 2016
16313-09-Pb- 4	Beige Wall Paint - 1301 Rankin		April 11, 2016
16313-09-Pb- 5	Blue/Beige/Light Green Wall Paint - 1306 Rankin		April 11, 2016
Client Sample # (s):	16313-09-Pb-01 - 16313-09-Pb-05	Total # of Samples:	5
Relinquished (Client):	Steven Gore	Date: April 18, 2016	Time:
Received (Lab):		Date:	Time:
Comments/Special Instructions:			

Signature

01-13-13 PM:55 OUT

Rankin