

## Location Summary Report

<b>Client Name:</b> Windsor -ESSEX Community Housing Corporation (CHC)							<b>Building Address:</b> 1323 Tilston Ave												
							<b>Building Name / Description:</b> Bridgeview I /												
<b>Location Name:</b> 972 Rankin Ave							<b>Location Number:</b> 68				<b>Area of Location:</b> 800			<b>Floor:</b> 1					
<b>Consultant Name:</b> ECOH							<b>Last Survey Date:</b> 2016-04-04				<b>Last Re-assessment Date:</b>								

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION								SAMPLE NUMBER	RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with dark streaks	N	E	150	0	0	150	SF			v	002-ASB	None Detected	None Detected	Priority 3	
1.1	Floor	Laminate Flooring	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
1.2	Floor	Hard Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
2.0	Walls	Plaster	N/A	Plaster	N	A	100	0	0	100	SF			s	008-ASB	None Detected	None Detected	Priority 3	
3.0	Ceiling	Plaster	N/A	Plaster	Please Select	C	800	0	0	800	SF			v	008-ASB	None Detected	None Detected	Priority 3	
4.0	Structure	Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Mechanical	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Other	Heat Sheild	N/A	Heat Sheild	Y	D	3	0	0	3	SF			v	009-ASB	Chrysotile 40%	Confirmed Asbestos	Priority 3	

**Comments :** Detached - 2 Story with 3 Bedrooms  
 1 - Flooring VFT2 in kitchen under laminate flooring.