

Summary of Asbestos Bulk Samples

Client Name: Windsor –ESSEX Community Housing Corporation (CHC)								Building Address: 1377 Askin Ave				
								Building Name / Description: Bridgeview II /				
DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
001-ASB	16313-10-ASB-01A	12	Floor	Vinyl Floor Tiles	VFT1	12"x 12" Beige with Brown Streaks.	N/A	None Detected	N/A	None Detected	None Detected	
	16313-10-ASB-01B	12	Floor	Vinyl Floor Tiles	VFT1	12"x 12" Beige with Brown Streaks.	N/A	None Detected	N/A	None Detected		
	16313-10-ASB-01C	12	Floor	Vinyl Floor Tiles	VFT1	12"x 12" Beige with Brown Streaks.	N/A	None Detected	N/A	N/A		
002-ASB	16313-10-ASB-02A	24	Floor	Vinyl Floor Tiles	VFT2	12"x 12" Beige with Brown, Yellow and Blue specks.	N/A	None Detected	N/A	None Detected	None Detected	
	16313-10-ASB-02B	24	Floor	Vinyl Floor Tiles	VFT2	12"x 12" Beige with Brown, Yellow and Blue specks.	N/A	None Detected	N/A	None Detected		
	16313-10-ASB-02C	24	Floor	Vinyl Floor Tiles	VFT2	12"x 12" Beige with Brown, Yellow and Blue specks.	N/A	None Detected	N/A	None Detected		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
003-ASB	16313-10-ASB-03A	23	Floor	Vinyl Sheet Flooring	VSF1	Beige with Stoney Pattern	N/A	None Detected	N/A	N/A	None Detected	
	16313-10-ASB-03B	23	Floor	Vinyl Sheet Flooring	VSF1	Beige with Stoney Pattern	N/A	None Detected	N/A	None Detected		
	16313-10-ASB-03C	23	Floor	Vinyl Sheet Flooring	VSF1	Beige with Stoney Pattern	N/A	None Detected	N/A	N/A		
				Vinyl Sheet Flooring		Beige Sandy Pattern with Blue Dots	N/A	None Detected	N/A	None Detected	None Detected	
004-ASB	16313-10-ASB-04A	22	Floor	Vinyl Sheet Flooring	VSF4	Beige Sandy Pattern with Blue Dots	N/A	None Detected	N/A	None Detected		
	16313-10-ASB-04B	22	Floor	Vinyl Sheet Flooring	VSF4	Beige Sandy Pattern with Blue Dots	N/A	None Detected	N/A	None Detected		
	16313-10-ASB-04C	22	Floor	Vinyl Sheet Flooring	VSF4	Beige Sandy Pattern with Blue Dots	N/A	None Detected	N/A	None Detected		
	16313-10-ASB-05A	12	Ducts	Tar Paper	N/A	Tar Paper	N/A	None Detected	N/A	N/A		
005-ASB											None Detected	
	16313-10-ASB-05B	12	Ducts	Tar Paper	N/A	Tar Paper	N/A	None Detected	N/A	N/A		
	16313-10-ASB-05C	12	Ducts	Tar Paper	N/A	Tar Paper	N/A	None Detected	N/A	N/A		

DB SAMPLE NUMBER	SAMPLE NUMBER	LOCATION NUMBER	SYSTEM	MATERIAL	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LAYER ONE TYPE	LAYER ONE PERCENT %	LAYER TWO TYPE	LAYER TWO PERCENT %	HAZARD	COMMENTS
006-ASB	16313-10-ASB-06A	22	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	Chrysotile	1	N/A	N/A	Confirmed Asbestos	
	16313-10-ASB-06B	6	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		
	16313-10-ASB-06C	10	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		
	16313-10-ASB-06D	24	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		
	16313-10-ASB-06E	24	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		
	16313-10-ASB-06F	23	Walls	Drywall and Joint Compound	N/A	Drywall and Joint Compound	N/A	Not Analyzed	N/A	N/A		