

## Location Summary Report

<b>Client Name:</b> Windsor -ESSEX Community Housing Corporation (CHC)							<b>Building Address:</b> 1323 Tilston Ave											
							<b>Building Name / Description:</b> Bridgeview I /											
<b>Location Name:</b> 1306 Rankin Ave							<b>Location Number:</b> 19				<b>Area of Location:</b> 600			<b>Floor:</b> 1				
<b>Consultant Name:</b> ECOH							<b>Last Survey Date:</b> 2016-04-04				<b>Last Re-assessment Date:</b>							

  

SN	SYSTEM	MATERIAL	MATERIAL ID	MATERIAL DESCRIPTION	FRIABILITY (Y/N)	ACCESS	QUANTITY/CONDITION							SAMPLE NUMBER		RESULTS	HAZARD	ACTION	ESTIMATED COST
							GOOD	FAIR	POOR	TOTAL	UNITS	DEBRIS	UNITS						
1.0	Floor	Vinyl Floor Tiles	VFT2	12"x12" Beige with dark streaks	N	A	75	0	0	75	SF			s	002-ASB	None Detected	None Detected	Priority 3	
1.1	Floor	Vinyl Floor Tiles	VFT3	9"x 9" Black with light brown streak	N	A	40	0	0	40	SF			s	003-ASB	Chrysotile 2%	Confirmed Asbestos	Priority 3	
1.2	Floor	Vinyl Sheet Flooring	VSF1	Square Pattern	Y	A	25	0	0	25	SF			v	0000	None Detected	None Detected	Priority 3	
2.0	Walls	Plaster	N/A	Plaster	N	A	80	0	0	80	%			s	008-ASB	None Detected	None Detected	Priority 3	
2.1	Walls	Concrete Block	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
3.0	Ceiling	Plaster	N/A	Plaster	N	C	450	0	0	450	SF			Please Select	008-ASB	None Detected	None Detected	Priority 3	
4.0	Structure	Wood	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
5.0	Piping	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
6.0	Ducts	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
7.0	Mechanical	Uninsulated	-	-	-	-	-	-	-	-	-	-	-	-	-	-	No Asbestos	-	
8.0	Other	Heat Shield	N/A	Heat Shield	Y	D	8	0	0	8	SF			s	009-ASB	Chrysotile 40%	Confirmed Asbestos	Priority 3	

**Comments :** 1 Story with 3 Bedroom  
 VFT 2 in Kitchen, VFT3 Basement Stairwell, VSF1 new in Washroom.  
 8.0 - Heat Shield in vents.