



Document Number: SCN067053

Revision: A

Group: Scanned (Hardcopy) Item

Type: Environmental Reports - Svs Ctr

State: Released

Latest Released: YES

Implemented Date: 08/01/2019

Stamp Date: Thursday, August 1, 2019 9:29:19 AM EST

viewLinc Alarm Report

Report name	ETHICON Quarterly Report
Alarm events	from 2019-04-01 12:00:00 to 2019-07-01 12:00:00
Report generated on	2019-07-01 12:05:24 (UTC-05:00) Eastern Time (US & Canada)
Include zones and locations:	System/ETHICON
Include alarm details:	No
Include system alarms:	Yes
Include device communication alarms:	Yes
Include device configuration alarms:	Yes
Include device validation alarms:	Yes
Include device calibration alarms:	Yes
Include threshold alarms:	Yes
Include threshold categories:	Alarms Only

Summary

Total active alarms:	72
Activated alarms:	72
Deactivated alarms:	72
Acknowledged alarms:	66

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-04-16 14:41:38	2019-04-16 14:42:51	1 minute, 12 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-04-16 14:50:23 by lbtar1 (Ibrahim Bitar): "See Comments", comment: The alarm was caused by a disruption in the network connection. The alarm was on for less than 2 minutes and when the network connection was restored, there weren't any alarm that were tripped other than the connection alarm. No action were taken.
2019-04-16 14:41:38	2019-04-16 14:43:01	1 minute, 23 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-04-16 14:50:23 by lbtar1 (Ibrahim Bitar): "See Comments", comment: The alarm was caused by a disruption in the network connection. The alarm was on for less than 2 minutes and when the network connection was restored, there weren't any alarm that were tripped other than the connection alarm. No action were taken.
2019-04-16 14:41:38	2019-04-16 14:42:51	1 minute, 12 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-04-16 14:50:23 by lbtar1 (Ibrahim Bitar): "See Comments", comment: The alarm was caused by a disruption in the network connection. The alarm was on for less than 2 minutes and when the network connection was restored, there weren't any alarm that were tripped other than the connection alarm. No action were taken.
2019-04-16 14:41:39	2019-04-16 14:42:50	1 minute, 11 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-04-16 14:50:23 by lbtar1 (Ibrahim Bitar): "See Comments", comment: The alarm was caused by a disruption in the network connection. The alarm was on for less than 2 minutes and when the network connection was restored, there weren't any alarm that were tripped other than the connection alarm. No action were taken.
2019-04-16 14:41:41	2019-04-16 14:42:51	1 minute, 9 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-04-16 14:50:23 by lbtar1 (Ibrahim Bitar): "See Comments", comment: The alarm was caused by a disruption in the network connection. The alarm was on for less than 2 minutes and when the network connection was restored, there weren't any alarm that were tripped other than the connection alarm. No action were taken.
2019-04-21 07:05:39	2019-04-22 13:55:03	1 day, 6 hours, 49 minutes, 24 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-04-22 09:26:40 by lbtar1 (Ibrahim Bitar): "Used paper system", comment: Alarm communication alarms came on Sunday morning. The alarm is a communication alarm. We are currently recording temperature & humidity on FRM003931 until the alarms are resolved.

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-04-21 07:05:39	2019-04-22 13:55:04	1 day, 6 hours, 49 minutes, 24 seconds	Device ETHIC-RepairTsl2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTsl2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-04-22 09:26:40 by lbtar1 (Ibrahim Bitar): "Used paper system", comment: Alarm communication alarm came on Sunday morning. The alarm is a communication alarm. We are currently recording temperature & humidity on FRM003931 until the alarms are resolved.
2019-04-21 07:05:39	2019-04-22 13:55:02	1 day, 6 hours, 49 minutes, 23 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-04-22 09:26:40 by lbtar1 (Ibrahim Bitar): "Used paper system", comment: Alarm communication alarm came on Sunday morning. The alarm is a communication alarm. We are currently recording temperature & humidity on FRM003931 until the alarms are resolved.
2019-04-21 07:05:39	2019-04-22 13:55:03	1 day, 6 hours, 49 minutes, 23 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-04-22 09:26:40 by lbtar1 (Ibrahim Bitar): "Used paper system", comment: Alarm communication alarm came on Sunday morning. The alarm is a communication alarm. We are currently recording temperature & humidity on FRM003931 until the alarms are resolved.
2019-04-21 07:05:42	2019-04-22 13:55:03	1 day, 6 hours, 49 minutes, 21 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-04-22 09:26:40 by lbtar1 (Ibrahim Bitar): "Used paper system", comment: Alarm communication alarm came on Sunday morning. The alarm is a communication alarm. We are currently recording temperature & humidity on FRM003931 until the alarms are resolved.

Acknowledged on 2019-04-22 09:26:40
by lbtar1 (Ibrahim Bitar): "Used paper
system", comment: Alarm communication
alarm came on Sunday morning. The
alarm is a communication alarm. We are
currently recording temperature &
humidity on FRM003931 until the alarms
are resolved.

Acknowledged on 2019-04-22 09:26:40
by lbtar1 (Ibrahim Bitar): "Used paper
system", comment: Alarm communication
alarm came on Sunday morning. The
alarm is a communication alarm. We are
currently recording temperature &
humidity on FRM003931 until the alarms
are resolved.

Acknowledged on 2019-04-22 09:26:40
by lbtar1 (Ibrahim Bitar): "Used paper
system", comment: Alarm communication
alarm came on Sunday morning. The
alarm is a communication alarm. We are
currently recording temperature &
humidity on FRM003931 until the alarms
are resolved.

Acknowledged on 2019-04-22 09:26:40
by lbtar1 (Ibrahim Bitar): "Used paper
system", comment: Alarm communication
alarm came on Sunday morning. The
alarm is a communication alarm. We are
currently recording temperature &
humidity on FRM003931 until the alarms
are resolved.

Acknowledged on 2019-04-22 09:26:40
by lbtar1 (Ibrahim Bitar): "Used paper
system", comment: Alarm communication
alarm came on Sunday morning. The
alarm is a communication alarm. We are
currently recording temperature &
humidity on FRM003931 until the alarms
are resolved.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-01 15:53:00	2019-05-01 15:53:58	58 seconds	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T Min value: 76.03 °F Max value: 76.03 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-05-01 16:02:08	2019-05-01 16:02:30	22 seconds	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T Min value: 76.03 °F Max value: 76.03 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-05-01 16:03:12	2019-05-01 16:07:11	3 minutes, 59 seconds	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T Min value: 76.03 °F Max value: 76.03 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-05-01 16:10:13	2019-05-01 16:15:16	5 minutes, 3 seconds	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T Min value: 76.03 °F Max value: 76.03 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-05-01 16:17:23	2019-05-01 16:25:30	8 minutes, 7 seconds	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T Min value: 76.03 °F Max value: 76.07 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-05-01 16:26:31	2019-05-01 16:43:43	17 minutes, 12 seconds	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON High Temperature Warning for High Threshold: location value greater than 76.00 °F for System/ETHICON/Repair & Testing2 T Min value: 76.03 °F Max value: 76.07 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-08 10:37:38	2019-05-08 10:39:41	2 minutes, 2 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-08 10:42:41 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 10:37:38	2019-05-08 10:39:41	2 minutes, 2 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-05-08 10:42:41 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 10:37:38	2019-05-08 10:39:41	2 minutes, 2 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-08 10:42:41 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 10:37:39	2019-05-08 10:39:38	1 minute, 59 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-08 10:42:40 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 10:37:39	2019-05-08 10:39:41	2 minutes, 2 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-08 10:42:41 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:15:07	2019-05-08 11:16:07	1 minute	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-09 08:31:55 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-08 11:15:07	2019-05-08 11:16:04	57 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-09 08:45:11 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:15:07	2019-05-08 11:16:07	1 minute	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:44:49 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:15:07	2019-05-08 11:16:07	1 minute	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-05-09 08:48:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:15:07	2019-05-08 11:16:05	57 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-09 08:43:03 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:25:21	2019-05-08 11:27:22	2 minutes, 1 second	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-05-08 11:31:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:25:21	2019-05-08 11:27:19	1 minute, 58 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-08 11:31:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-08 11:25:21	2019-05-08 11:27:22	2 minutes, 1 second	Device ETHIC-RepairTst2 (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-08 11:31:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:25:21	2019-05-08 11:27:22	2 minutes	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-08 11:31:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:25:21	2019-05-08 11:27:22	2 minutes	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-08 11:31:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:31:19	2019-05-08 11:32:27	1 minute, 7 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-09 08:32:16 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:34:26	2019-05-08 11:35:26	1 minute	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-09 08:44:40 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:36:32	2019-05-08 11:39:16	2 minutes, 44 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-09 08:32:38 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 3 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-08 11:36:32	2019-05-08 11:39:16	2 minutes, 43 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-09 08:37:40 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 3 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:36:32	2019-05-08 11:39:16	2 minutes, 43 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-09 08:37:53 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 3 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:36:32	2019-05-08 11:39:16	2 minutes, 43 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-05-09 08:38:11 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 3 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:36:33	2019-05-08 11:39:13	2 minutes, 40 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:38:25 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 3 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:48:22	2019-05-08 11:50:23	2 minutes, 1 second	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-09 08:41:49 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:48:22	2019-05-08 11:50:24	2 minutes, 1 second	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:42:18 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-08 11:48:22	2019-05-08 11:50:21	1 minute, 58 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-09 08:37:25 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:48:22	2019-05-08 11:50:23	2 minutes, 1 second	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-05-09 08:42:10 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:48:22	2019-05-08 11:50:24	2 minutes, 1 second	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-09 08:42:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 2 minutes. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:53:25	2019-05-08 11:54:27	1 minute, 1 second	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-09 08:42:45 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:53:25	2019-05-08 11:54:24	58 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:46:08 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:53:25	2019-05-08 11:54:26	1 minute, 1 second	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-09 08:44:23 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-08 11:53:25	2019-05-08 11:54:24	58 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-05-09 08:47:57 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 11:53:25	2019-05-08 11:54:24	58 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2019-05-09 08:31:16 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 12:20:49	2019-05-08 12:21:45	55 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-05-09 08:48:13 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 13:46:08	2019-05-08 13:47:11	1 minute, 3 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2019-05-09 08:42:53 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 15:56:19	2019-05-08 15:57:24	1 minute, 5 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:45:53 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-08 17:04:49	2019-05-08 17:05:51	1 minute, 2 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:45:41 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-09 02:35:49	2019-05-09 02:37:02	1 minute, 13 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-05-09 08:53:20 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. COM Port timed out and came back. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-09 02:36:06	2019-05-09 02:36:59	53 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-05-09 08:45:24 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-09 02:36:06	2019-05-09 02:37:02	55 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-05-09 08:31:38 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-09 02:36:06	2019-05-09 02:36:57	50 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-05-09 08:44:07 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-09 02:36:07	2019-05-09 02:37:02	55 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-05-09 08:49:36 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication alarm went off for 1 minute. The temperature and humidity were within the operating and storage thresholds before the alarm tripped and after the communication was restored.
2019-05-23 18:52:15	2019-05-23 18:58:33	6 minutes, 17 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-06-17 11:38:15 by ibitar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-05-23 18:52:25	2019-05-23 18:58:33	6 minutes, 7 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (1918), Repair & Testing T (1916)	Acknowledged on 2019-06-17 11:38:15 by lbtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-05-23 18:52:26	2019-05-23 18:57:32	5 minutes, 6 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (1926), Spare parts & Shipping T (1924)	Acknowledged on 2019-06-17 11:38:15 by lbtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-05-23 18:52:26	2019-05-23 18:58:33	6 minutes, 6 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (1922), Repair & Testing2 T (1920)	Acknowledged on 2019-06-17 11:38:15 by lbtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-05-23 18:52:26	2019-05-23 19:06:33	14 minutes, 6 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (1912), Receiving&Decontamination T (1914)	Acknowledged on 2019-06-17 11:38:15 by lbtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-06-17 11:12:57	2019-06-17 11:21:58	9 minutes, 1 second	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (1922), Repair & Testing2 T (1920)	Acknowledged on 2019-06-17 11:38:15 by lbtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-06-17 11:12:57	2019-06-17 11:18:59	6 minutes, 1 second	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-06-17 11:38:15 by Ibtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-06-17 11:12:57	2019-06-17 11:18:59	6 minutes, 1 second	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-06-17 11:38:15 by Ibtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-06-17 11:12:57	2019-06-17 11:21:00	8 minutes, 3 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-06-17 11:38:15 by Ibtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-06-17 11:12:57	2019-06-17 11:18:59	6 minutes, 1 second	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-06-17 11:38:15 by Ibtar1 (Ibrahim Bitar): "No action taken", comment: There was a power outage that had caused the internet network to go down. The power outage happened during the technician's lunch break therefore there weren't any products that were being worked. Communications was back up under 5 minutes.
2019-06-30 08:00:05	2019-07-01 08:39:26	1 day, 0 hours, 39 minutes, 21 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-07-01 08:39:26 by Ibtar1 (Ibrahim Bitar): "Calibration Scheduled with Vaisala", comment: Calibration on the units themselves is not out until late September. We have reached out to Vaisala and they have placed us on their schedule to complete the calibration.

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-06-30 08:00:05	2019-07-01 08:39:04	1 day, 0 hours, 38 minutes, 59 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com	Device Calibration Reminder: ETHICON ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-07-01 08:39:04 by Ibtar1 (Ibrahim Bitar): "Reached out to Vaisala", comment: Calibration on the units themselves is not out until late September. We have reached out to Vaisala and they have placed us on their schedule to complete the calibration.
2019-06-30 08:00:05	2019-07-01 08:39:58	1 day, 0 hours, 39 minutes, 53 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-07-01 08:39:58 by Ibtar1 (Ibrahim Bitar): "Calibration Scheduled with Vaisala", comment: Calibration on the units themselves is not out until late September. We have reached out to Vaisala and they have placed us on their schedule to complete the calibration.
2019-06-30 08:00:18	2019-07-01 08:38:14	1 day, 0 hours, 37 minutes, 56 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-07-01 08:38:14 by Ibtar1 (Ibrahim Bitar): "Calibration Scheduled with Vaisala", comment: Calibration on the units themselves is not out until late September. We have reached out to Vaisala and they have placed us on their schedule to complete the calibration.
2019-06-30 08:00:19	2019-07-01 08:39:40	1 day, 0 hours, 39 minutes, 21 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-07-01 08:39:39 by Ibtar1 (Ibrahim Bitar): "Calibration Scheduled with Vaisala", comment: Calibration on the units themselves is not out until late September. We have reached out to Vaisala and they have placed us on their schedule to complete the calibration.

Name: Eric Smith
Date: 7/11/19
Signature:



Time zone: (UTC-05:00) Eastern Time (US & Canada)

Name: Robert Peters
Date: 7/12/19
Signature:



Name: Ibrahim Bitar
Date: 7-1-2019
Signature:

