



Document Number: SCN075743

Revision: A

Group: Scanned (Hardcopy) Item

Type: Environmental Reports - Svs Ctr

State: Released

Latest Released: YES

Implemented Date: 05/13/2020

Stamp Date: Wednesday, May 13, 2020 6:06:17 AM EST

viewLinc Alarm Report

| | |
|--------------------------------------|--|
| Report name | ETHICON Quarterly Report |
| Alarm events | from 2020-01-01 12:12:31 to 2020-04-01 12:12:31 |
| Report generated on | 2020-04-01 12:17:16 (UTC-05:00) Eastern Time (US & Canada) |
| Include zones and locations: | System/ETHICON |
| Include alarm details: | No |
| Include system alarms: | Yes |
| Include device communication alarms: | Yes |
| Include device configuration alarms: | Yes |
| Include device validation alarms: | Yes |
| Include device calibration alarms: | Yes |
| Include threshold alarms: | Yes |
| Include threshold categories: | Alarms Only |

Summary

| | |
|----------------------|----|
| Total active alarms: | 77 |
| Activated alarms: | 72 |
| Deactivated alarms: | 72 |
| Acknowledged alarms: | 72 |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|---------------------------|---|--|---|
| 2019-12-21 18:01:53 | 2019-12-21 18:32:48 | 30 minutes, 55 seconds | Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-01-05 14:37:04 by smith6 (Steven Smith): "Acknowledged all "off" alarms", comment: no action |
| 2019-12-21 18:01:53 | 2019-12-21 18:32:47 | 30 minutes, 54 seconds | Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-01-05 14:37:05 by smith6 (Steven Smith): "Acknowledged all "off" alarms", comment: no action |
| 2019-12-21 18:01:53 | 2019-12-21 18:32:47 | 30 minutes, 54 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914) | Acknowledged on 2020-01-05 14:37:06 by smith6 (Steven Smith): "Acknowledged all "off" alarms", comment: no action |
| 2019-12-21 18:01:53 | 2019-12-21 18:32:47 | 30 minutes, 54 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-01-05 14:37:07 by smith6 (Steven Smith): "Acknowledged all "off" alarms", comment: no action |
| 2019-12-21 18:01:53 | 2019-12-21 18:32:47 | 30 minutes, 53 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-01-05 14:37:08 by smith6 (Steven Smith): "Acknowledged all "off" alarms", comment: no action |
| 2020-01-05 14:36:38 | 2020-01-05 14:45:11 | 8 minutes, 33 seconds | Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com | Device Configuration Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-01-06 08:43:34 by ibitar1 (Ibrahim Bitar): "no action taken" |
| 2020-01-08 15:42:30 | 2020-01-08 15:43:44 | 1 minute, 13 seconds | Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-01-08 15:47:08 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Device shutdown causing communication alarm. Alarm was triggered for only one minute therefore did not have any product effect. No actions were taken as system restored in under 2 minutes. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|---------------------------|---|---|--|
| 2020-01-08 15:42:30 | 2020-01-08 15:44:02 | 1 minute, 31 seconds | Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-01-08 15:47:07 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Device shutdown triggered for only one minute therefore did not have any product effect. No actions were taken as system restored in under 2 minutes. |
| 2020-01-08 15:42:31 | 2020-01-08 15:44:02 | 1 minute, 31 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914) | Acknowledged on 2020-01-08 15:47:08 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Device shutdown triggered for only one minute therefore did not have any product effect. No actions were taken as system restored in under 2 minutes. |
| 2020-01-08 15:42:33 | 2020-01-08 15:43:43 | 1 minute, 10 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-01-08 15:47:09 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Device shutdown causing communication alarm. Alarm was triggered for only one minute therefore did not have any product effect. No actions were taken as system restored in under 2 minutes. |
| 2020-01-08 15:42:33 | 2020-01-08 15:44:02 | 1 minute, 29 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-01-08 15:47:08 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Device shutdown triggered for only one minute therefore did not have any product effect. No actions were taken as system restored in under 2 minutes. |
| 2020-01-16 20:48:45 | 2020-01-16 21:06:59 | 18 minutes, 14 seconds | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | |
| 2020-01-17 02:27:52 | 2020-01-17 02:29:04 | 1 minute, 12 seconds | Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-01-17 06:22:27 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Communication Alarm has occurred for a duration of 1 minute. Product wasn't effected as the communication alarm occurred for a short duration. No actions were taken. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|--|--|--|---|
| 2020-01-17 02:27:52 | 2020-01-17 02:29:35 | 1 minute, 43 seconds | Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-01-17 06:22:27 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Communication Alarm has occurred for a duration of 1 minute. Product wasn't effected as the communication alarm occurred for a short duration. No actions were taken. |
| 2020-01-17 02:27:52 | 2020-01-17 02:29:05 | 1 minute, 12 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914) | Acknowledged on 2020-01-17 06:22:27 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Communication Alarm has occurred for a duration of 1 minute. Product wasn't effected as the communication alarm occurred for a short duration. No actions were taken. |
| 2020-01-17 02:27:54 | 2020-01-17 02:29:07 | 1 minute, 12 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-01-17 06:22:27 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Communication Alarm has occurred for a duration of 1 minute. Product wasn't effected as the communication alarm occurred for a short duration. No actions were taken. |
| 2020-01-17 02:27:54 | 2020-01-17 02:29:37 | 1 minute, 42 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-01-17 06:22:27 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Communication Alarm has occurred for a duration of 1 minute. Product wasn't effected as the communication alarm occurred for a short duration. No actions were taken. |
| 2020-01-22 19:33:40 | 2020-01-23 09:49:15 | 14 hours, 15 minutes, 35 seconds | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 22.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922) | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 22.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922) | |
| 2020-01-22 19:35:12 | 2020-01-23 09:34:11 | 13 hours, 58 minutes, 59 seconds | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 23.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|--|--|---|---|
| 2020-01-22 21:52:37 | 2020-01-23 09:10:21 | 11 hours, 17 minutes, 44 seconds | Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH | Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 22.8 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922) | Acknowledged on 2020-01-23 09:22:10 by ibitar1 (Ibrahim Bitar): "Repairs completed on Repair & Testing floor Repair & Testing floor began to leak over night. Technicians did not operate on products that were affected during the LowLow alarm state. Facilities completed over night repairs and we were out of the alarm state on both by 9:11 AM. |
| 2020-01-22 22:00:40 | 2020-01-23 08:54:52 | 10 hours, 54 minutes, 12 seconds | Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH | Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH Min value: 23.0 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | Acknowledged on 2020-01-23 09:22:10 by ibitar1 (Ibrahim Bitar): "Repairs completed on Repair & Testing floor completed", comment: Humidifiers on Repair & Testing floor began to leak over night. Technicians did not operate on products that were affected during the LowLow alarm state. Facilities completed over night repairs and we were out of the alarm state on both by 9:11 AM. |
| 2020-02-06 03:32:55 | 2020-02-06 03:33:59 | 1 minute, 3 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-14 10:41:04 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was during non servicing hours. No actions were taken. |
| 2020-02-14 04:55:40 | 2020-02-14 04:55:54 | 14 seconds | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | |
| 2020-02-14 08:17:17 | 2020-02-14 08:18:29 | 1 minute, 11 seconds | Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 08:17:19 | 2020-02-14 08:18:29 | 1 minute, 9 seconds | Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|-------------------------|--|--|--|
| 2020-02-14 08:17:19 | 2020-02-14 08:18:50 | 1 minute, 30 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-14 11:30:28 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 08:17:19 | 2020-02-14 08:18:29 | 1 minute, 9 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924) | Acknowledged on 2020-02-14 11:30:26 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 08:17:20 | 2020-02-14 08:18:29 | 1 minute, 9 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930) | Acknowledged on 2020-02-14 11:30:27 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 08:57:58 | 2020-02-14 08:59:59 | 2 minutes, 1 second | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918) | |
| 2020-02-14 10:26:32 | 2020-02-14 10:27:58 | 1 minute, 26 seconds | Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916) | Acknowledged on 2020-02-14 11:30:28 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:26:34 | 2020-02-14 10:27:58 | 1 minute, 24 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-14 11:30:25 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:26:34 | 2020-02-14 10:27:38 | 1 minute, 4 seconds | Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920) | Acknowledged on 2020-02-14 11:30:25 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:26:34 | 2020-02-14 10:27:38 | 1 minute, 4 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924) | Acknowledged on 2020-02-14 11:30:26 by Ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|-------------------------|--|--|--|
| 2020-02-14 10:26:35 | 2020-02-14 10:27:39 | 1 minute, 4 seconds | Device ETHIC-Warehouse Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:32:39 | 2020-02-14 10:33:49 | 1 minute, 10 seconds | Device ETHIC-RepairTst2 Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:32:41 | 2020-02-14 10:34:08 | 1 minute, 27 seconds | Device ETHIC-RepairTst2 Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:32:41 | 2020-02-14 10:34:08 | 1 minute, 27 seconds | Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:32:41 | 2020-02-14 10:33:53 | 1 minute, 11 seconds | Device ETHIC-Spare&Ship on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-02-14 11:30:26 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-14 10:32:41 | 2020-02-14 10:34:08 | 1 minute, 26 seconds | Device ETHIC-Warehouse Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-02-14 11:30:27 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 03:34:44 | 2020-02-17 03:36:11 | 1 minute, 27 seconds | Device ETHIC-RepairTst2 Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-02-17 09:09:49 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 03:34:46 | 2020-02-17 03:36:12 | 1 minute, 25 seconds | Device ETHIC-RepairTst2 Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-02-17 09:09:50 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|-------------------------|---|---|--|
| 2020-02-17 03:34:46 | 2020-02-17 03:35:49 | 1 minute, 3 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-17 09:09:51 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 03:34:47 | 2020-02-17 03:36:10 | 1 minute, 23 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping T (11924) (11926),Spare parts & Shipping T (11924) | Acknowledged on 2020-02-17 09:09:47 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 03:34:47 | 2020-02-17 03:35:50 | 1 minute, 2 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930) | Acknowledged on 2020-02-17 09:09:48 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 08:35:01 | 2020-02-17 08:36:47 | 1 minute, 45 seconds | Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916) | Acknowledged on 2020-02-17 09:09:48 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 08:35:03 | 2020-02-17 08:36:24 | 1 minute, 20 seconds | Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920) | Acknowledged on 2020-02-17 09:09:48 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 08:35:04 | 2020-02-17 08:36:21 | 1 minute, 17 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-17 09:09:49 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 08:35:04 | 2020-02-17 08:36:47 | 1 minute, 43 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924) | Acknowledged on 2020-02-17 09:09:50 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 08:35:04 | 2020-02-17 08:36:21 | 1 minute, 17 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930) | Acknowledged on 2020-02-17 09:09:47 by ibitar1 (Ibrahim Bitar): "no action taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|-------------------------|--|--|--|
| 2020-02-17 09:12:32 | 2020-02-17 09:13:53 | 1 minute, 21 seconds | Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-02-20 08:26:16 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 09:12:34 | 2020-02-17 09:14:21 | 1 minute, 46 seconds | Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-02-20 08:26:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 09:12:34 | 2020-02-17 09:14:17 | 1 minute, 42 seconds | Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914) | Acknowledged on 2020-02-20 08:26:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 09:12:35 | 2020-02-17 09:13:53 | 1 minute, 18 seconds | Device ETHIC-Spare&Ship on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-02-20 08:26:15 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-17 09:12:35 | 2020-02-17 09:14:19 | 1 minute, 44 seconds | Device ETHIC-Warehouse on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-02-20 08:26:15 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-19 16:24:40 | 2020-02-19 16:25:37 | 56 seconds | Device ETHIC-Spare&Ship on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-02-20 08:26:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-19 17:21:10 | 2020-02-19 17:22:30 | 1 minute, 19 seconds | Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-02-20 08:26:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-19 17:21:10 | 2020-02-19 17:22:19 | 1 minute, 8 seconds | Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-02-20 08:26:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|---------------------------------------|---|---|--|
| 2020-02-19 17:21:10 | 2020-02-19 17:22:29 | 1 minute, 19 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-20 08:26:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-19 17:21:11 | 2020-02-19 17:22:19 | 1 minute, 8 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924) | Acknowledged on 2020-02-20 08:26:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-19 17:21:13 | 2020-02-19 17:22:19 | 1 minute, 6 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930) | Acknowledged on 2020-02-20 08:26:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication issue caused the Alarm. Alarm was for a short duration before restoration. No actions were taken. |
| 2020-02-23 05:06:36 | 2020-02-23 10:53:13 | 5 hours, 46 minutes, 37 seconds | Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916) | Acknowledged on 2020-02-23 10:53:12 by admin (Administration super user): "", comment: Location alarming paused |
| 2020-02-23 05:06:36 | 2020-02-23 10:53:34 | 5 hours, 46 minutes, 57 seconds | Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920) | Acknowledged on 2020-02-23 10:53:33 by admin (Administration super user): "", comment: Location alarming paused |
| 2020-02-23 05:06:36 | 2020-02-23 10:52:53 | 5 hours, 46 minutes, 16 seconds | Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914) | Acknowledged on 2020-02-23 10:52:53 by admin (Administration super user): "", comment: Location alarming paused |
| 2020-02-23 05:06:37 | 2020-02-23 10:53:51 | 5 hours, 47 minutes, 14 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924) | Acknowledged on 2020-02-23 10:53:51 by admin (Administration super user): "", comment: Location alarming paused |
| 2020-02-23 05:06:37 | 2020-02-23 10:54:17 | 5 hours, 47 minutes, 39 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930) | Acknowledged on 2020-02-23 10:54:17 by admin (Administration super user): "", comment: Location alarming paused |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|-------------------------|---|--|--|
| 2020-02-24 00:52:18 | 2020-02-24 00:53:17 | 59 seconds | Device ETHIC-Rec&Decon Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-02-24 07:19:59 by ibitar1 (Ibrahim Bitar): "No Action Taken. Occurred during non servicing/working hours. Communication error occurred for about 1 minute and the communication was restored afterwards. |
| 2020-02-24 00:52:18 | 2020-02-24 00:53:18 | 59 seconds | Device ETHIC-Rec&Decon Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-02-24 07:19:59 by ibitar1 (Ibrahim Bitar): "No Action Taken. Occurred during non servicing/working hours. Communication error occurred for about 1 minute and the communication was restored afterwards. |
| 2020-02-24 00:52:18 | 2020-02-24 00:53:39 | 1 minute, 20 seconds | Device ETHIC-Rec&Decon Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914) | Acknowledged on 2020-02-24 07:19:59 by ibitar1 (Ibrahim Bitar): "No Action Taken. Occurred during non servicing/working hours. Communication error occurred for about 1 minute and the communication was restored afterwards. |
| 2020-02-24 00:52:18 | 2020-02-24 00:53:17 | 58 seconds | Device ETHIC-Spare&Ship Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-02-24 07:19:59 by ibitar1 (Ibrahim Bitar): "No Action Taken. Occurred during non servicing/working hours. Communication error occurred for about 1 minute and the communication was restored afterwards. |
| 2020-02-24 00:52:21 | 2020-02-24 00:53:17 | 56 seconds | Device ETHIC-Warehouse Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-02-24 07:19:59 by ibitar1 (Ibrahim Bitar): "No Action Taken. Occurred during non servicing/working hours. Communication error occurred for about 1 minute and the communication was restored afterwards. |
| 2020-03-05 15:14:01 | 2020-03-05 15:15:02 | 1 minute, 1 second | Device ETHIC-Rec&Decon Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-03-05 08:24:19 by ibitar1 (Ibrahim Bitar): "No Action Taken. Communication Alarm only lasted 1 minute and the communication was restored. |
| 2020-03-12 12:47:35 | 2020-03-12 12:48:27 | 51 seconds | Device ETHIC-Rec&Decon Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916) | Acknowledged on 2020-03-16 15:37:28 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: COM port miscommunication caused this alarm. Alarm was in a duration for one minute. No actions was taken as the alarm only lasted for one minute. |
| 2020-03-16 01:28:24 | 2020-03-16 01:29:26 | 1 minute, 2 seconds | Device ETHIC-Rec&Decon Enterprise Server ITSUSRAWSP04243.jnj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920) | Acknowledged on 2020-03-16 15:37:28 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: COM port miscommunication caused this alarm. Alarm was in a duration for one minute. No actions was taken as the alarm only lasted for one minute. |

| Activation | Deactivation | Duration | Source | Description | Acknowledgement |
|------------------------|------------------------|------------|--|--|--|
| 2020-03-23 01:14:24 | 2020-03-23 01:15:23 | 59 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-03-23 15:03:36 by Ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required. |
| 2020-03-28 13:57:04 | 2020-03-28 13:58:00 | 55 seconds | Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Warehouse RH (11928), Warehouse T (11930) | Acknowledged on 2020-04-01 12:07:48 by Ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required. |
| 2020-03-28 13:57:04 | 2020-03-28 13:58:00 | 55 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-04-01 12:07:48 by Ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required. |
| 2020-03-29 02:08:24 | 2020-03-29 02:09:19 | 55 seconds | Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com | Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924) | Acknowledged on 2020-04-01 12:07:48 by Ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required. |

Name: Eric Smith
Date:
Signature:

Name: Robert Peters
Date:
Signature:

Name: Ibrahim Bitar
Date: 04-01-2020
Signature: 