



**Document Number: SCN074278**

**Revision: A**

**Group: Scanned (Hardcopy) Item**

**Type: Environmental Reports - Svs Ctr**

**State: Released**

**Latest Released: YES**

**Implemented Date: 03/20/2020**

**Stamp Date: Friday, March 20, 2020 7:55:48 AM EST**

## viewLinc Alarm Report

Report name	ETHICON Quarterly Report
Alarm events	from 2019-10-01 12:00:00 to 2020-01-01 12:00:00
Report generated on	2020-01-01 12:02:39 (UTC-05:00) Eastern Time (US & Canada)
Include zones and locations:	System/ETHICON
Include alarm details:	No
Include system alarms:	Yes
Include device communication alarms:	Yes
Include device configuration alarms:	Yes
Include device validation alarms:	Yes
Include device calibration alarms:	Yes
Include threshold alarms:	Yes
Include threshold categories:	Alarms Only

### Summary

Total active alarms:	72
Activated alarms:	72
Deactivated alarms:	72
Acknowledged alarms:	18

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-10-02 15:02:40	2019-10-02 15:06:38	3 minutes, 57 seconds	Device ETHIC-RepairTst2 (17332042) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst (17332042) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-10-14 16:01:22 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-02 15:02:40	2019-10-02 15:06:38	3 minutes, 58 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-10-14 16:04:42 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-02 15:02:40	2019-10-02 15:06:38	3 minutes, 57 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-10-14 15:59:02 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-02 15:02:42	2019-10-02 15:06:38	3 minutes, 55 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-10-14 16:04:20 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-02 15:02:43	2019-10-02 15:06:38	3 minutes, 55 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-10-14 16:01:01 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-07 04:08:17	2019-10-07 04:09:18	1 minute	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-10-14 16:05:58 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-10-12 09:29:40	2019-10-12 09:39:05	9 minutes, 24 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-10-14 16:08:08 by Ibitari (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-12 09:29:40	2019-10-12 09:37:46	8 minutes, 5 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-10-14 16:08:09 by Ibitari (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-12 09:29:40	2019-10-12 09:35:44	6 minutes, 3 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-10-14 16:08:08 by Ibitari (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-12 09:29:41	2019-10-12 09:35:45	6 minutes, 4 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-10-14 16:08:08 by Ibitari (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-10-12 09:29:41	2019-10-12 09:37:46	8 minutes, 5 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-10-14 16:08:08 by Ibitari (Ibrahim Bitar): "No Action Taken", comment: Communication error had caused this alarm. There was no major effect as the data was reloaded right after the duration that there was a communication error. No Actions were taken.
2019-11-12 07:35:37	2019-11-12 07:40:46	5 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-11-12 07:41:54	2019-11-12 07:43:01	1 minute, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-11-12 07:44:09	2019-11-12 07:45:19	1 minute, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-11-12 19:48:11	2019-11-12 19:49:12	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-11-12 19:53:14	2019-11-12 19:54:14	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-11-12 23:50:58	2019-11-12 23:51:55	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-11-13 02:21:59	2019-11-13 02:23:40	1 minute, 41 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-11-13 02:24:06	2019-11-13 02:25:03	57 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-11-13 02:46:03	2019-11-13 02:48:40	2 minutes, 37 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-11-13 03:06:12	2019-11-13 03:07:12	1 minute	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-11-13 03:25:19	2019-11-13 07:55:09	4 hours, 29 minutes, 50 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.71 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-11-13 03:45:28	2019-11-13 03:45:40	12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-11-13 06:18:57	2019-11-13 06:37:05	18 minutes, 8 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-11-13 06:38:05	2019-11-13 06:41:10	3 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-11-13 06:42:07	2019-11-13 06:43:07	1 minute	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-11-13 06:45:08	2019-11-13 06:46:12	1 minute, 4 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-11-13 06:48:09	2019-11-13 07:02:15	14 minutes, 6 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-11-16 02:34:35	2019-11-16 02:35:36	1 minute	Device ETHIC-RepairT s12 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairT s12 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-12-05 14:59:57 by ibitar1 (Ibrahim Bitar): "See Comments", comment: There was a communication issue that had caused the sensors to disconnect from the server for 1-2 minutes. No actions were taken as communication was restored and data was uploaded.
2019-11-25 10:12:23	2019-11-25 10:13:57	1 minute, 33 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-12-05 14:59:56 by ibitar1 (Ibrahim Bitar): "See Comments", comment: There was a communication issue that had caused the sensors to disconnect from the server for 1-2 minutes. No actions were taken as communication was restored and data was uploaded.

Time zone: (UTC-05:00) Eastern Time (US & Canada)



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-11-25 11:54:13	2019-11-25 11:55:40	1 minute, 27 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-12-05 14:59:55 by ibitar1 (Ibrahim Bitar). "See Comments", comment: There was a communication issue that had caused the sensors to disconnect from the server for 1-2 minutes. No actions were taken as communication was restored and data was uploaded.
2019-11-25 14:03:31	2019-11-25 14:04:26	55 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-12-05 14:59:56 by ibitar1 (Ibrahim Bitar). "See Comments", comment: There was a communication issue that had caused the sensors to disconnect from the server for 1-2 minutes. No actions were taken as communication was restored and data was uploaded.
2019-12-02 11:22:51	2019-12-02 11:23:52	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-02 11:24:52	2019-12-02 11:30:40	5 minutes, 48 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 10:59:47	2019-12-05 13:15:14	2 hours, 15 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 30.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-12-05 11:00:40	2019-12-05 11:03:01	2 minutes, 21 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-12-05 11:05:09	2019-12-05 11:19:53	14 minutes, 44 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 11:21:20	2019-12-05 11:22:17	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 11:25:40	2019-12-05 11:27:04	1 minute, 24 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 11:33:46	2019-12-05 11:35:40	1 minute, 54 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 11:38:23	2019-12-05 11:39:47	1 minute, 24 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 11:48:38	2019-12-05 11:49:54	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-12-05 11:51:25	2019-12-05 11:52:24	59 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 11:55:40	2019-12-05 11:59:59	4 minutes, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 12:03:12	2019-12-05 12:06:30	3 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 12:07:30	2019-12-05 12:16:15	8 minutes, 45 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 13:18:40	2019-12-05 13:19:26	46 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-12-05 13:33:45	2019-12-05 16:43:18	3 hours, 9 minutes, 33 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-12-05 13:50:02	2019-12-05 15:22:22	1 hour, 32 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 28.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 14:12:20	2019-12-05 14:24:38	12 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH Min value: 28.7 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2019-12-05 15:14:08 by Ibtar1 (Ibrahim Bitar): "Products were not being Operated", comment: Caused because of maintenance on the HVAC System. Products that are effected were not being operated from 2:10 to 2:48. System is being restored and alarms were restored back in threshold ranges.
2019-12-05 14:13:26	2019-12-05 14:46:56	33 minutes, 30 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.3 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Acknowledged on 2019-12-05 15:14:08 by Ibtar1 (Ibrahim Bitar): "Products were not being Operated", comment: Caused because of maintenance on the HVAC System. Products that are effected were not being operated from 2:10 to 2:48. System is being restored and alarms were restored back in threshold ranges.
2019-12-05 14:48:02	2019-12-05 14:51:11	3 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.9 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Acknowledged on 2019-12-05 15:14:08 by Ibtar1 (Ibrahim Bitar): "Products were not being Operated", comment: Caused because of maintenance on the HVAC System. Products that are effected were not being operated from 2:10 to 2:48. System is being restored and alarms were restored back in threshold ranges.
2019-12-05 15:23:30	2019-12-05 15:32:46	9 minutes, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 15:33:52	2019-12-05 15:34:58	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Time zone: (UTC-05:00) Eastern Time (US & Canada)



Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-12-05 16:43:40	2019-12-05 16:44:27	47 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-12-05 18:18:17	2019-12-05 18:27:21	9 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-05 18:26:21	2019-12-05 18:39:30	13 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-12-10 11:50:40	2019-12-10 11:55:24	4 minutes, 44 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-10 19:51:29	2019-12-10 19:53:27	1 minute, 58 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-10 19:55:33	2019-12-10 19:56:39	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Time zone: (UTC-05:00) Eastern Time (US & Canada)




Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-12-10 23:55:40	2019-12-10 23:56:52	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-18 16:45:40	2019-12-18 16:45:57	17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-18 20:51:04	2019-12-18 20:52:04	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-19 00:41:45	2019-12-19 00:42:56	1 minute, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-19 00:46:06	2019-12-19 00:47:12	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-19 04:44:00	2019-12-19 04:45:03	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-12-19 04:45:40	2019-12-19 04:46:09	29 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-12-21 18:01:53	2019-12-21 18:32:48	30 minutes, 55 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSPO4243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSPO4243.jni.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	
2019-12-21 18:01:53	2019-12-21 18:32:47	30 minutes, 54 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSPO4243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSPO4243.jni.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	
2019-12-21 18:01:53	2019-12-21 18:32:47	30 minutes, 54 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSPO4243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSPO4243.jni.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	
2019-12-21 18:01:53	2019-12-21 18:32:47	30 minutes, 54 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSPO4243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSPO4243.jni.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	
2019-12-21 18:01:53	2019-12-21 18:32:47	30 minutes, 53 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSPO4243.jni.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSPO4243.jni.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	

Name: Eric Smith  
Date: 03-17-2020  
Signature: 

Name: Robert Peters  
Date: 3/10/2020  
Signature: 

Name: Ibrahim Bilar  
Date: 03-04-2020  
Signature: 