

T5 probe 4

Program used	Upi2
Materiel used	-circle alignment fixture -UPI weight fixture -real mems /non working -UPI tube -0.015 solder ring -pcb attached to ferrite core
Result for vacuum	failed
Result for over pressure	n/a
Reason for failure	Waiting to be investigated
date	10/18/2023
operator	Jaikob williams
Investigate by	UPI team