

## Maintenance Checklist Report #4913634

---

Date: 2023-11-18

Machine ID	Equipment	Service Type	Operator	Duration	Site	Comments
MC-231	Lathe	Preventive	Anna Nowak	3.1	Plant 1C	Worn gasket replaced.
MC-211	Assembly Robot	Corrective	Anna Nowak	3.0	Plant 2B	Calibration check OK.
MC-229	Laser Cutter	Inspection	Laura Rossi	2.0	Plant 2B	Wooden pallet checked.
MC-230	Packaging Line	Preventive	Peter Schmidt	2.7	Plant 3A	No issues found.
MC-224	Laser Cutter	Inspection	Carlos Garcia	1.6	Plant 3A	Worn gasket replaced.
MC-288	Laser Cutter	Corrective	Laura Rossi	2.3	Plant 3A	No issues found.
MC-228	Assembly Robot	Preventive	Jan Kowalski	2.5	Plant 2B	
MC-206	Assembly Robot	Corrective	Anna Nowak	3.3	Plant 2B	Replaced fuse (5A).
MC-259	Packaging Line	Preventive	Carlos Garcia	3.1	Plant 1C	Refilled oil (HLP 46).

This log summary supports the asset-management dashboard. All maintenance durations are recorded for performance metrics. Overall equipment condition is satisfactory post-maintenance. Ensure that each service entry has the required approvals. Maintenance notes are archived for compliance audits.

Lubrication Checked	N/A
Calibration Verified	N/A
Emergency Stop Tested	No

Authorized by: \_\_\_\_\_ Operator: \_\_\_\_\_