

Equipment Record Report

2025-07-14

Use this summary to forecast parts replacement and resource needs. Refer to the maintenance register for detailed service histories. The equipment log below includes fault codes and corrective notes. This maintenance extract is prepared for compliance audit trails.

Spare Parts Used:

| Part Name | Part No. | Qty Used |
|---------------------|----------|----------|
| Switch Assembly | P-4033 | 3 |
| Sensor Module | P-3279 | 5 |
| Li-Ion Battery Pack | P-2271 | 5 |
| Li-Ion Battery Pack | P-8544 | 4 |

| Machine ID | Equipment | Type | Technician | Downtime | Previous Service | Site | Comments |
|------------|-----------------|------------|---------------|----------|------------------|--------------------------|----------|
| MC-236 | Plasma Cutter | Corrective | Laura Rossi | 3.1 | 2023-09-25 | Replaced fuse (5A). | |
| MC-224 | Hydraulic Press | Preventive | Peter Schmidt | 1.9 | 2024-12-17 | | |
| MC-267 | Hydraulic Press | Inspection | Peter Schmidt | 3.8 | 2024-05-21 | | |
| MC-289 | Paint Booth | Preventive | Jan Kowalski | 1.6 | 2025-05-06 | Replaced coolant. | |
| MC-238 | Laser Cutter | Preventive | Jan Kowalski | 2.5 | 2024-01-31 | Replaced coolant. | |
| MC-282 | Assembly Robot | Corrective | Anna Nowak | 3.8 | 2025-06-27 | Tightened loose bolts. | |
| MC-253 | Assembly Robot | Inspection | Laura Rossi | 3.8 | 2024-01-27 | Refilled oil (HLP 46). | |
| MC-284 | Paint Booth | Corrective | Laura Rossi | 3.4 | 2023-08-25 | Switch contacts cleaned. | |
| MC-251 | Laser Cutter | Corrective | Anna Nowak | 2.9 | 2024-11-07 | Calibration check OK. | |

| | |
|----------------|---------------|
| Authorized by: | Laura Rossi |
| Operator: | Carlos Garcia |