

Maintenance Checklist Report #1164671

Date: 2025-07-09

Unit Code	Machine	Type	Operator	Duration	Site	Notes
MC-272	Assembly Robot	Preventive	Carlos Garcia	3.1	Plant 2B	Refilled oil (HLP 46).
MC-246	Laser Cutter	Preventive	Laura Rossi	2.3	Plant 1C	Wooden pallet checked.
MC-236	Plasma Cutter	Inspection	Laura Rossi	3.7	Plant 3A	No issues found.
MC-202	Lathe	Inspection	Laura Rossi	3.6	Plant 2B	Replaced fuse (5A).
MC-255	Packaging Line	Preventive	Anna Nowak	1.8	Plant 1C	Calibration check OK.
MC-267	Packaging Line	Corrective	Anna Nowak	3.5	Plant 2B	Alignment of hinges adjusted.
MC-251	Packaging Line	Corrective	Jan Kowalski	3.6	Plant 1C	Sensor recalibrated.
MC-245	Hydraulic Press	Corrective	Carlos Garcia	2.7	Plant 1C	Replaced fuse (5A).

All maintenance tasks have been completed as per schedule. Check remaining life-cycles of key components from this report. Overall equipment condition is satisfactory post-maintenance. No critical faults were found during the latest inspection. This log summary supports the asset-management dashboard.

Lubrication Checked	Yes
Calibration Verified	No
Emergency Stop Tested	No

Authorized by: _____ Operator: _____