

## Machine Log Summary

Performed On: 2023-08-10

Signed off:	Laura Rossi
Performed by:	Peter Schmidt

This maintenance extract is prepared for compliance audit trails. Use this summary to forecast parts replacement and resource needs. Please review this log for recent service dates, types, and remarks. Refer to the maintenance register for detailed service histories. Ensure all safety checks were completed during servicing.

### Section A:

Machine ID	MC-203	MC-291	MC-228	MC-221	MC-275	MC-255
Machine	Hydraulic Press	Laser Cutter	Paint Booth	Laser Cutter	Assembly Robot	Conveyor Belt
Service Type	Preventive	Inspection	Inspection	Corrective	Preventive	Preventive
Operator	Carlos Garcia	Jan Kowalski	Anna Nowak	Laura Rossi	Carlos Garcia	Carlos Garcia
Downtime	2.7	2.0	3.2	3.9	4.0	2.2
Notes	Sensor recalibrated.	Tightened loose bolts.	Refilled oil (HLP 46).	Wooden pallet checked.	Changed oil and filters.	Replaced fuse (5A).

### Section B:

Machine ID	MC-291	MC-221	MC-255	MC-275	MC-203	MC-232
Machine	Laser Cutter	Laser Cutter	Conveyor Belt	Assembly Robot	Hydraulic Press	Conveyor Belt
Service Type	Inspection	Inspection	Inspection	Corrective	Preventive	Inspection
Operator	Peter Schmidt	Peter Schmidt	Carlos Garcia	Laura Rossi	Peter Schmidt	Peter Schmidt
Downtime	1.9	3.1	2.3	2.2	3.7	1.6
Notes	Sensor recalibrated.	Changed oil and filters.	Refilled oil (HLP 46).	Changed oil and filters.	Li-Ion battery pack serviced.	No issues found.

Uptime (%)	Error Count	Notes
92.34%	3	Bolt tightened